9 JOPPA ROAD PORTOBELLO EAST EDINBURGH EH15 2HA



Home Report

shepherd.co.uk



All Angles Covered

Residential | Commercial | Property & Construction



Energy Performance Certificate



Energy Performance Certificate (EPC)

Dwellings

Scotland

9 JOPPA ROAD, PORTOBELLO EAST, EDINBURGH, EH15 2HA

Dwelling type: Semi-detached house

Date of assessment: 10 July 2024
Date of certificate: 17 July 2024
Total floor area: 118 m²

Primary Energy Indicator: 291 kWh/m²/year

Reference number: 0130-2540-7130-2094-6865 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

You can use this document to:

- . Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£6,825	See your recommendations
Over 3 years you could save*	£3,102	report for more information

^{*} based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (61)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band E (54)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Internal or external wall insulation	£4,000 - £14,000	£927.00
2 Floor insulation (suspended floor)	£800 - £1,200	£327.00
3 Low energy lighting	£40	£216.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, as built, no insulation (assumed)	or limestone, as built, no insulation ★★☆☆ ★★☆	
Roof	Pitched, 200 mm loft insulation	****	★★★ ☆
Floor	Suspended, no insulation (assumed)	_	_
Windows	Some double glazing	****	****
Main heating	Boiler and radiators, mains gas	****	★★★ ☆
Main heating controls	Programmer, room thermostat and TRVs	****	★★★ ☆
Secondary heating	None	_	_
Hot water	From main system, no cylinder thermostat	***	***
Lighting	Low energy lighting in 33% of fixed outlets	***	***

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 51 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 6.1 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 3.9 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£5,097 over 3 years	£2,910 over 3 years	
Hot water	£1,086 over 3 years	£423 over 3 years	You could
Lighting	£642 over 3 years	£390 over 3 years	save £3,102
Total	£6,825	£3,723	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.


Recommended measures		Indicative cost	Typical saving	Rating after improvement	
Re	commended measures	Indicative cost	per year	Energy	Environment
1	Internal or external wall insulation	£4,000 - £14,000	£309	D 67	D 61
2	Floor insulation (suspended floor)	£800 - £1,200	£109	D 68	D 63
3	Low energy lighting for all fixed outlets	£40	£72	C 69	D 64
4	Hot water cylinder thermostat	£200 - £400	£129	C 71	D 67
5	Replace boiler with new condensing boiler	£2,200 - £3,000	£176	C 74	C 71
6	Solar water heating	£4,000 - £6,000	£76	C 75	C 73
7	Replace single glazed windows with low- E double glazed windows	£3,300 - £6,500	£163	C 78	C 77
8	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£486	B 86	B 84

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

Micro CHP

Choosing the right improvement package





About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long-lasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

3 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

4 Cylinder thermostat

A hot water cylinder thermostat enables the boiler to switch off when the water in the cylinder reaches the required temperature; this minimises the amount of energy that is used and lowers fuel bills. The thermostat is a temperature sensor that sends a signal to the boiler when the required temperature is reached. To be fully effective it needs to be sited in the correct position and hard wired in place, so it should be installed by a competent plumber or heating engineer. Building regulations apply to this work, so it is best to check with your local authority building standards department whether a building warrant will be required.

5 Condensing boiler

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

6 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

7 Double glazed windows

Double glazing is the term given to a system where two panes of glass are made up into a sealed unit. Replacing existing single-glazed windows with double-glazed windows will improve comfort in the home by reducing draughts and cold spots near windows. Double-glazed windows may also reduce noise, improve security and combat problems with condensation. Building regulations apply to this work and planning permission may also be required, so it is best to check with your local authority on what standards need to be met. A building warrant is not required if the windows comply with the current requirements.

8 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	15,556	N/A	(60)	(3,131)
Water heating (kWh per year)	3,450			_

Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

About this document

Phone number:

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:
Assessor membership number:
Company name/trading name:
Address:

Mr. Darren Lewis
EES/016141
J & E Shepherd
12 Atholl Crescent
Edinburgh

EH3 8HA 0131 225 1234

Email address: edinburgh@shepherd.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT





Scottish
Single Survey



survey report on:

Property address	9 JOPPA ROAD PORTOBELLO EAST EDINBURGH EH15 2HA
Customer	Mr R Robinson (Executry)
Customer address	9 Joppa Road Portobello East Edinburgh EH15 2HA
Prepared by	J & E Shepherd
Date of inspection	10th July 2024



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report ² will be from information contained in the Report and the generic Mortgage Valuation Report.

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3. Category 1: No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a two storey semi detached house.
Accommodation	Ground Floor: Entrance hall, kitchen/dining room, bedroom and family bathroom. First Floor: Living room, two bedrooms, study and wc apartment.
Gross internal floor area (m²)	118m2 approx.
Neighbourhood and location	The subjects are situated within an established residential area of mixed style properties lying within the Joppa area of Edinburgh and convenient for local shopping, educational and social facilities.
Age	1800 approx.
Weather	Dry but overcast.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate. Masonry type chimney stacks present.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate. Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally. Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and

	I manufacture de la constant de la c
	reasonable to do so.
	The roof is pitched and slated with flat sections present over the wc apartment.
[
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	PVC and cast iron rainwater goods noted. A parapet gutter is present.
Г	
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are built of traditional solid stonework pointed externally together with render finishes and pointed brickwork is present to the rear elevation.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows throughout are of a mixed type with both timber and UPVC type units present. The access door is of a timber variety.
External decorations	Visually inspected.
	Painted timber and UPVC finishes.
Conservatories / porches	Visually inspected.
	None.
Communal areas	Circulation areas visually inspected.
	None.
Garages and permanent outbuildings	Visually inspected.
	The property benefits from a workshop located to the rear elevation. This is of a masonry type with a pitched roof clad with felt.

Outside areas and boundaries	Visually inspected.
	The property benefits from garden grounds to the front and rear elevations. A driveway is present to the rear elevation. This is accessed via the rear lane. The boundaries are of a mixed type.
Ceilings	Visually inspected from floor level.
	Plaster finishes noted.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Plaster finishes noted. Timber panelling is present to sections of the internal walls.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	The floors throughout have fitted floor coverings.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	The kitchen fittings are of wall and base type. The internal doors, skirtings and facings appear to be of timber variety.
Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	Presumed blocked over.
Internal decorations	Visually inspected.
	Papered and painted throughout.
Cellars	Visually inspected where there was a safe and purpose-built access.
	None noted.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. Mains supply.
	ινιαιτίο ουμμίν.

Gas Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. Mains supply. Water, plumbing, bathroom fittings Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances. Water is from the mains supply. The plumbing, where seen, is of copper supply pipes and PVC waste pipes, however, due to the age of the property it is possible that that lead plumbing is present. The sanitary fittings comprise a four piece suite in the bathroom and two piece suite in the wc apartment. Heating and hot water Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. The property benefits from a gas fired central heating system with the gas boiler located within the dining room cupboard. Hot water appears to be provided via the hot water cylinder located in the dining room cupboard. An electric fire is present in the living room. Drainage Drainage covers etc. were not lifted. Neither drains nor drainage systems were tested. Presumed to main public sewer. Fire, smoke and burglar alarms Visually inspected. No tests whatsoever were carried out to the system or appliances. All Scottish homes require a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also needs to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon-fuelled appliance such as a boiler, open fire or wood burner, a carbon monoxide detector is

ownership.

also required. We have not assessed or tested any existing

equipment and it is the purchasers responsibility to confirm that the property will comply with these standards following a change of

Any additional limits to inspection

For flats / maisonettes

Only the subject flat and internal communal areas giving access to the flat were inspected.

If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.

The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

The property was fully floor covered at the time of inspection. A number of the cupboards were full of possessions at the time of inspection. No access was gained to any sub floor areas. No access was gained to the area below the sanitary fittings. Head and shoulders access only gained to the roof void due to the presence of insulation and lack of access boarding. The roof decks and chimneys were seen from restricted ground floor views only. The roof and rainwater goods were not monitored under wet weather conditions. At the time of inspection conditions were dry. The services were not tested. The heating system was not tested. The flat roof deck was unseen.

An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1 Chimney pots
- (2) Coping stone
- 3) Chimney head
- 4) Flashing
- (5) Ridge ventilation
- 6) Ridge board
- 7) Slates / tiles
- (8) Valley guttering
- 9 Dormer projection
- 10 Dormer flashing
- 11 Dormer cheeks
- 12) Sarking
- 13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
 - 7) Parapet gutter
- 18) Eaves guttering
- 19) Rainwater downpipe
- 0) Verge boards /skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- (25) Window pointing
- 26) Window sills
- (27) Rendering
- (28) Brickwork / pointing
- (29) Bay window projection
- (30) Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- 39) Water tank
- 40) Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	

Structural movement	
Repair category	2
Notes	Structural movement was noted to the subject property in particular in the form of cracking and distortions to the external walls and cracking and distortions to the internal walls and ceilings. We would also point out that deflections were noted to the roof. We would therefore recommend that that a Structural Engineer carryout a precautionary check of the entire property prior to purchase including the roof void area and provide written estimates for any necessary remedial works.

Dampness, rot and infestation	
Repair category	2
Notes	Unacceptable levels of dampness were noted to sections of the wall linings at ground floor level together with leakage to the ceilings at first floor level and wood boring insect infestation was noted within the roof void area. We would recommend that a timber/damp specialist contractor carry out a thorough inspection of the entire property prior to purchase and provide written estimates for all necessary remedial works including exposure works.

Chimney stacks	
Repair category	2
Notes	Defective chimney stacks noted. Remedial works required by a suitable contractor.

Roofing including roof space	
Repair category	2
Notes	Deflections and staining were noted to the roof. Loose and cracked slates noted. Leakage noted to the ceiling at first floor level. The flat roof decks will have a limited lifespan and were unseen. Remedial works are required and advice should be sought from a Roofing Contractor prior to purchase and estimates

obtained for all necessary remedial works.
--

Rainwater fittings	
Repair category	2
Notes	Corrosion noted to sections of the rainwater goods. Parapet gutters are present. Parapet gutters can be a source of timber decay and dampness and vegetation was noted to the guttering. Remedial works are required including repairs to adjacent areas if necessary. All rainwater goods should be monitored under prolonged downpour conditions. At the time of inspection conditions were dry.

Main walls	
Repair category	2
Notes	Weathering, cracking and distortions noted to the external walls. Remedial works required by a suitable contractor.

Windows, external doors and joinery	
Repair category	2
Notes	The windows are dated and showing signs of timber decay and require a full upgrade and any failed double glazed units replaced. Ongoing maintenance to the access door should be anticipated.

External decorations	
Repair category	2
Notes	A full upgrade of the external decoration is required.

Conservatories/porches	
Repair category	-
Notes	None.

Communal areas	
Repair category	-
Notes	None.

Garages and permanent outbuildings	
Repair category	2
Notes	Dampness noted to the walls within the workshop and the felt roof decks are dated. A full upgrade of the workshop is required by a suitable contractor.

Outside areas and boundaries	
Repair category	3
Notes	The boundary walls are deflected and have been temporarily supported. The retaining walls are showing signs of distortions and cracking. The garden walls/external access steps are showing signs of spalling. The timber fencing is showing signs of weathering. Remedial works required by a suitable contractor and estimates should be obtained prior to purchase.

Ceilings	
Repair category	2
Notes	Plaster defects noted including the cornicing. Remedial works required and estimates should be obtained prior to purchase.

Internal walls	
Repair category	2
Notes	Plaster cracking noted. Remedial works required by a suitable contractor.

Floors including sub-floors	
Repair category	2
Notes	Loose and springy flooring noted. Remedial works required.

Internal joinery and kitchen fittings	
Repair category	1
Notes	We would recommend that safety glass be installed to internal areas. Minor refitting required to internal doors.

Chimney breasts and fireplaces	
Repair category	1
Notes	Prior to use any fireplace, flue or chimney should be checked and made good by a suitable contractor.

Internal decorations	
Repair category	2
Notes	The internal decoration would benefit from upgrading.

Cellars	
Repair category	-
Notes	None.

Electricity	
Repair category	2
Notes	Sections of the electrical wiring system are dated and recommend the system be checked and upgraded by a Registered Electrician prior to purchase. No tests were carried out by this firm.

Gas	
Repair category	1
Notes	We presume the gas supply is free of defects, however, the system has not been tested

Water, plumbing and bathroom fittings	
Repair category	2
Notes	The sanitary fittings are dated. We presume the sealants around the sanitary fittings are functional and no defects are present to the adjacent areas. A precautionary check of the areas below and adjacent to the sanitary fittings is always recommended prior to purchase as these areas are prone to leakage. We would recommend that any sections of lead plumbing be replaced using conventional material.

Heating and hot water	
Repair category	2
Notes	The hot water cylinder and boiler are dated We would recommend they be checked and upgraded by a suitable heating contractor and any necessary remedial works carried out. No tests were carried out by this firm.

The electric fire is dated.	
-----------------------------	--

Drainage	
Repair category	2
Notes	A precautionary check of the drainage system is recommended prior to purchase in accordance with good practice.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	2
Dampness, rot and infestation	2
Chimney stacks	2
Roofing including roof space	2
Rainwater fittings	2
Main walls	2
Windows, external doors and joinery	2
External decorations	2
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	2
Outside areas and boundaries	3
Ceilings	2
Internal walls	2
Floors including sub-floors	2
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	2
Cellars	-
Electricity	2
Gas	1
Water, plumbing and bathroom fittings	2
Heating and hot water	2
Drainage	2

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground and First
2. Are there three steps or fewer to a main entrance door of the property?	Yes No X
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes No X

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

It is presumed all documentation is available for alterations to the subject property, in particular alterations to the bathroom, formation of the workshop, alterations to the kitchen/dining room, installation of replacement windows and formation of the wc apartment. We would also point out the rear access lane is not adopted.

The vendor has informed us that remedial works were carried out to the rear access lane due to collapsed drain by Scottish Water and all documentation relating to this should be obtained prior to purchase.

A full upgrade of the workshop is required.

Where areas of maintenance, defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialists or contractors advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

Estimated reinstatement cost for insurance purposes

For Reinstatement Cost Assessment purposes, it is recommended that the subjects be insured for a sum of not less than £550,000 (Five Hundred and Fifty Thousand Pounds Sterling). This figure is the estimate of the cost of rebuilding the premises and bears no direct relationship to current market value.

Valuation and market comments

Having considered matters, taking account of our general observations on site, we are of the opinion that the Market Value of the subjects in their present condition and with the benefit of vacant possession may be fairly stated in the sum of £475,000 (Four Hundred and Seventy Five Thousand Pounds Sterling).

Market conditions are steady at the present time.

Signed	Security Print Code [577539 = 7170] Electronically signed
Report author	D Lewis
Company name	J & E Shepherd
Address	12 Atholl Crescent, Edinburgh, EH3 8HA
Date of report	17th July 2024

Mortgage Valuation Report



Property Address	
Address Seller's Name Date of Inspection	9 JOPPA ROAD, PORTOBELLO EAST, EDINBURGH, EH15 2HA Mr R Robinson (Executry) 10th July 2024
Property Details	
Property Type	X House Bungalow Purpose built maisonette Converted maisonette Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)
Property Style	□ Detached X Semi detached □ Mid terrace □ End terrace □ Back to back □ High rise block □ Low rise block □ Other (specify in General Remarks)
Does the surveyor be e.g. local authority, mi	lieve that the property was built for the public sector, Yes X No ilitary, police?
Flats/Maisonettes only Approximate Year of 0	No. of units in block
Tenure	
X Absolute Ownership	Leasehold Ground rent £ Unexpired years
Accommodation	
Number of Rooms	3 Living room(s) 3 Bedroom(s) 1 Kitchen(s) 1 Bathroom(s) 1 WC(s) 0 Other (Specify in General remarks)
	cluding garages and outbuildings) 118 m² (Internal) m² (External) greater than 40%) X Yes No
Garage / Parking / 0	Outbuildings
Single garage Available on site?	□ Double garage X Parking space □ No garage / garage space / parking space X Yes □ No
Permanent outbuilding	gs:
None.	

Mortgage Valuation Report

Construction							
Walls	Brick	X Stone	Concrete	Timber frame	Other	r (specify in Gen	eral Remarks)
Roof	Tile	Slate	Asphalt	Felt	X Other	r (specify in Gen	eral Remarks)
Special Risks							
Has the property	suffered struc	tural movem	ent?			X Yes	No
If Yes, is this rece	ent or progres	sive?				Yes	X No
Is there evidence, immediate vicinity	•	ason to antic	ipate subsidence	, heave, landslip o	or flood in the	Yes	X No
If Yes to any of th	e above, prov	ride details in	General Remark	KS.			
Service Connec	ctions						
Based on visual ir of the supply in G			rices appear to be	e non-mains, pleas	se comment	on the type a	nd location
Drainage	X Mains	Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None				
Brief description of	of Central Hea	ıting:					
Gas fired with st	eel radiators.						
Site							
Apparent legal iss	sues to be ver	ified by the c	onveyancer. Ple	ase provide a brie	f description	in General R	emarks.
Rights of way	X Shared driv	es / access	Garage or other	amenities on separate	site Shar	red service conn	ections
Ill-defined boundar	ries	Agricu	ltural land included w	ith property	Othe	er (specify in Ge	neral Remarks)
Location							
X Residential suburb	Re	sidential within t	own / city	ed residential / comme	rcial Mair	nly commercial	
Commuter village	Re	mote village	Isola	ated rural property	Othe	er (specify in Ge	neral Remarks)
Planning Issues	s						
Has the property I If Yes provide det			d / altered?	Yes No			
Roads							
X Made up road	Unmade roa	d Parth	completed new road	Pedestrian a	ccess only	Adopted	Unadopted

Mortgage Valuation Report

	er			

At the time of inspection the property was found to require upgrading and the following observations were made:-

1. It is presumed all documentation is available for alterations to the subject property, in particular alterations to the bathroom, formation of the workshop, alterations to the kitchen/dining room, installation of replacement windows and formation of the wc apartment. We would also point out the rear access lane is not adopted. 2 The vendor has informed us that remedial works were carried out to the rear access lane due to collapsed drain by Scottish Water and all documentation relating to this should be obtained prior to purchase. 3. Unacceptable levels of dampness were noted to sections of the wall linings at ground floor level together with leakage to the ceilings at first floor level and wood boring insect infestation was noted within the roof void area. We would recommend that a timber/damp specialist contractor carry out a thorough inspection of the entire property prior to purchase and provide written estimates for all necessary remedial works including exposure works. 4. Repairs are required to the external fabric, in particular the main walls, roof, chimneys and rainwater goods. 5. The windows require to be upgraded. 6. Sections of the electrical wiring system are dated and recommend it be checked and upgraded by a Registered Electrician prior to purchase. 7. Upgrading required to the internal fabric. 8. The workshop requires to be upgraded.

The roof is pitched and slated with flat sections present.

Ess	ent	tial	Re	pai	rs

distortions and cracking. The garden walls/extern	temporarily supported. The retaining walls are showing signal access steps are showing signs of spalling. The timber all works required by a suitable contractor and estimates shown as the state of the	
Estimated cost of essential repairs £ uknown	Retention recommended? Yes X No Amount £	u/k

Mortgage Valuation Report

Comment on Mortgagea	bility			
	er suitable security for mortgage purposes subject the comments of the Sing criteria of any mortgage provider.	Structural		
Valuations				
Market value in present condition Market value on completion of essential repairs Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT) Is a reinspection necessary? Laterative 475,00 £ 175,00 £ 550,00 Tyes X				
Buy To Let Cases				
What is the reasonable rangmonth Short Assured Tenan	ge of monthly rental income for the property assuming a letting on a 6 ncy basis?	£		
Is the property in an area w	here there is a steady demand for rented accommodation of this type?	Yes No		
Declaration				
Signed	Security Print Code [577539 = 7170] Electronically signed by:-			
Surveyor's name	D Lewis			
Professional qualifications	BSC MRICS			
Company name	J & E Shepherd			
Address	12 Atholl Crescent, Edinburgh, EH3 8HA			
Telephone	0131 225 1234			
Fax	0131 220 3178			

17th July 2024

Report date



Property Questionnaire



9 Joppa Road,
Edinburgh,
EH15 2HA

Seller(s) Mrs Irene Robinson	
------------------------------	--

Completion date of property	08/07/2024
questionnaire	

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership								
	How long have you owned the property? 60 years								
2.	Council tax								
	Which Council Tax band is your property in? (Please tick one) ☐ A ☐ B ☐ C ☐ D ☐ E ☒ F ☐ G ☐ H								
з.	Parking								
	What are the arrangements for parking at your property? (Please tick all that apply)								
	• Garage								
	Allocated parking space								
	Driveway								
	Shared parking								
	On street								
	Resident permit								
	Metered parking								
	Other (please specify):								
4.	Conservation area								
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	☐ Yes ☐ No ☐ Don't know							

5.	Listed buildings		
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	⊠ Yes □ No	
6.	Alterations/additions/extensions	4.444	
а.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	☐ Yes ☑ No	
	If you have answered yes, please describe below the changes which you have made:		
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	☐ Yes	
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.		
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:		
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	☐ Yes ⊠ No	
	If you have answered yes, please answer the three questions below:	₩	
	(i) Were the replacements the same shape and type as the ones you replaced?	☐ Yes ☐ No	
	(ii) Did this work involve any changes to the window or door openings?	☐ Yes ☐ No	
	(iii) Please describe the changes made to the windows doors, or patio approximate dates when the work was completed):	doors (with	
Please give any guarantees which you received for this work to your solicitor or est agent.			

7.	Central heating	
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property— the main living room, the bedroom(s), the hall and the bathroom). If you have answered yes or partial—what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air). Gas If you have answered yes, please answer the three questions below:	⊠ Yes □ No □ Partial
	(i) When was your central heating system or partial central heat installed? 20 years ago	ing system
	(ii) Do you have a maintenance contract for the central heating system? If you have answered yes, please give details of the company with which you have a maintenance contract: June	⊠ Yes □ No
	(iii) When was your maintenance agreement last renewed? (Pleas month and year). June 2024	se provide the
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	☐ Yes ☑ No
9.	Issues that may have affected your property	
а.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it? If you have answered yes, is the damage the subject of any	☐ Yes ☑ No ☐ Yes
	outstanding Insurance claim?	☐ No
b.	Are you aware of the existence of asbestos in your property? If you have answered yes, please give details:	☐ Yes ☑ No

10.	Services					
a. Pi	a. Please tick which services are connected to your property and give details of the supplier:					
	Services	Connected	Supplier			
	Gas or liquid petroleum gas	yes	ovo			
	Water mains or private water supply	yes	scottish w	ater		
	Electricity	yes	ovo			
	Mains drainage	yes				
	Telephone	yes				
	Cable TV or satellite	no				
	Broadband	yes				
•			1			
b.	Is there a septic tank system a		ions below:	☐ Yes ☑ No		
	(iv) Do you have appropriate consents for the discharge from your septic tank?			☐ Yes ☐ No ☐ Don't Know		
	(v) Do you have a maintend If you have answered yes, pleat which you have a maintenance			☐ Yes ☐ No		

-

11.	Responsibilities for shared or common areas	
a,	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? If you have answered yes, please give details:	☐ Yes ☐ No ☑ Don't Know
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? If you have answered yes, please give details:	☐ Yes ☑ No ☐ Not applicable
c,	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	☐ Yes ☐ No
d.	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries? If you have answered yes, please give details:	☐ Yes ☑ No
e,	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details:	☐ Yes ☑ No
f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.) If you have answered yes, please give details:	☐ Yes ☑ No
12.	Charges associated with your property	
а.	Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	☐ Yes ⊠ No

b.	Is there a common buildings insurance policy? If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges? Please give details of any other charges you have to pay on a regula	☐ Yes ☐ No ☐ Don't Know ☐ Yes ☐ No ☐ Don't Know
	upkeep of common areas or repair works, for example to a residents maintenance or stair fund.	' association, or
13.	Specialist works	
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	☐ Yes ☑ No
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? If you have answered yes, please give details:	☐ Yes ☑ No
C.	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work? If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:	☐ Yes ☐ No

~

14.	Guarantees					
a.	Are there any guarantees or warranties for any of the following:					
		No	Yes	Don't know	With title deeds	Lost
(i)	Electrical work			\boxtimes		
(II)	Roofing	Ø				
(iii)	Central heating		Ø			
(iv)	National House Building Council (NHBC)	Ø				
(v)	Damp course	Ø				
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	×				
ь.	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):					
C.	Are there any outstanding claims under any of the guarantees listed above? If you have answered yes, please give details:					
15.	Boundaries					
	So far as you are aware, has any boundary of your property been moved in the last 10 years? If you have answered yes, please give details:					

16.	Notices that affe	ct your property	
	In the past three yea	ars have you ever received a notice:	
a.	advising that the own planning application?	ner of a neighbouring property has made a	⊠ Yes □ No
b.	that affects your pro	perty in some other way?	☐ Yes ☑ No
C.	that requires you to to your property?	do any maintenance, repairs or improvements	☐ Yes ☑ No
	If you have answered or estate agent, inclu of the purchaser of y	d yes to any of $a-c$ above, please give the notice and any notices which arrive at any time befoour property.	ces to your solicitor re the date of entry
/We		r(s)/or other authorised body or person nformation in this form is true and cor nd belief.	
Signa	iture(s):	gla Now Farmon	
)ate:	2/7	24	



Scottish
Single Survey







Survey Report



Client Name Mr Cran

Company Name Drummond Miller LLP

Client Property Address 9 Joppa Road

EDINBURGH Midlothian EH15 2HA

Email RCran@dm-property.com

Telephone Number 0131 243 1235

Surveyed by: William Mulgrew

Survey date: 16/07/2024

Survey reference: ENQ775209

Dear Mr Cran

Following my survey of the above property on 16/07/2024, I am pleased to enclose our Survey Report.

In accordance with your instructions, we have confined our inspection to the areas as indicated by you. If there are any omissions or if you believe that we have misinterpreted your survey instructions we apologise and if so we would be obliged if you could inform us as soon as possible so we can rectify any problems.

This Survey Report has been sub-divided into convenient sections so that you may easily find details of the survey, our recommendations and any quotations as applicable as well as other useful information.

In the meantime, if there are any points that you wish to discuss, you can contact me using the details below.

Yours sincerely

PROPERTY DESCRIPTION

The property is a Semi Detached Stone House.

WEATHER CONDITIONS

At the time of our visit to inspect the above property it was dry, therefore no comment can be made in regards to the efficiency of the rainwater goods.



OCCUPIED STATUS

At the time of our inspection the property was unoccupied.


LOCATION

Situations are described facing the front elevation of the property from Joppa Road.

EXTERNAL OBSERVATIONS

A brief external inspection of the property was completed from the ground level only during our visit and the following defects noted:

• Other defects





The external ground level in some areas are higher than the finished floor level internally, this could cause penetrating damp.

OBSERVATIONS

Roof Void

RESTRICTIONS

• Our inspection was restricted due to insulation and flooring, therefore we can only comment on the accessible rafters and cross ties.

General observations

Evidence of an infestation by the common furniture beetle (Anobium punctatum) was found to be present. This wood-boring insect is responsible for about 75% of all woodworm damage in this country and will attack softwood and hardwood.

There is evidence of past attack by old and apparently inactive common furniture beetle. No evidence of current woodworm insect infestation was detected.

TREATMENT RECOMMENDED

• We are unable to recommend any treatments at the moment on the basis of this inspection.

OBSERVATIONS

- First Floor Level
- All Areas

RESTRICTIONS

• The inspection of the property at this level was generally restricted by fixed floor coverings and no inspection to the floorboards was possible.

• General observations



Some water staining was noted to the ceiling within the room rear left, however observations from within the roof void did not indicate any fungal decay.





Some cracking and distortion was noted to the ceiling and cornice within the front rooms.

TREATMENT RECOMMENDED

• We are unable to recommend any treatments to this area at the moment on the basis of this inspection.

OBSERVATIONS

- Ground Floor Level
- All Areas

RESTRICTIONS

- The majority of the walls were framed and sheeted, therefore we could not access the original fabric of the building, our inspection is limited accordingly.
- The inspection of the property was generally restricted by fixed floor coverings and no inspection of the sub-floor was carried out.

General observations

Thank you for instructing Wise Property Care Ltd. to report on this property. We have confined our inspection to the accessible lower walls for evidence of dampness in accordance with your instructions.

Our inspection of the internal wall surfaces of the property was carried out by a visual inspection and by the use of an electrical conductivity meter; this indicated rising damp to be present in the walls designated for treatment on our enclosed sketch plan.

Rising dampness appears to be due to the apparent absence of an effective damp proof course.


Electrical Conductivity Meters are non-destructive and in masonry/brickwork will only show the presence or absence of moisture, not the type or the amount. They will only give a true reading with timber.

Destructive testing using a Calcium Carbide/Speedy meter will give the true free moisture content and can be carried out with the written permission of the owner as it involves drilling a number of holes into the masonry/brickwork as well as the removal of small sections of wall plaster in some cases. There is an additional fee for this testing and further details are available on request.

TREATMENT RECOMMENDED

- Place in a prominent position a warning notice and fire extinguisher as laid out in health and safety guidelines.
- Put in place protective polythene sheeting to the access and adjacent areas to minimise the damage from plaster dust which unfortunately is unavoidable.
- Remove 1 in number power socket and 2 in number radiators, lay a-side and subsequently refit on the completion of our detailed treatments.
- Remove skirting boards and lay aside for refixing.
- Prior to the insertion of our damp proof course, it is necessary to hack off and re-plaster all walls currently plastered on the 'hard' to a height of 1m above finished floor level. This re-plastering, which is solely designed to overcome the effects of hygroscopic salts, should be carried out in strict accordance with our enclosed specification and as per our attached sketch.
- 6A INJECTION CREAM TREATMENT: 12mm diameter holes drilled horizontally into the mortar joint at max. 120mm centres and to within a depth of 40mm from the opposite face.
- 6B INJECTION CREAM TREATMENT: Fill boreholes with injection cream using a low pressure sprayer or cartridge gun.
- Renew the wall plaster previously removed as per our standard specification No 8B, C & D.
- Refit skirting.
- All debris resulting from our works will be deposited into polythene bags and removed from site.
- Our specialist silicone diffusion cream is a cream for injection into brick or stonework etc. for the control of rising dampness. Our specialist silicone diffusion cream can be used in all types of masonry without the use of high pressure equipment. The cream is delivered by hand pressure only from a simple displacement pump and injector lance into a series of holes drilled into the mortar course. From here it diffuses into the masonry pores where the cream lines the pores with polysiloxanes. During the curing period a low molecular-weight silane vapour is also produced giving excellent migration through the wall. Curing of the DPC starts immediately with the final cure taking 2 6 weeks depending on wall thickness.

9 Joppa Road Edinburgh



CLIENT RESPONSIBILITIES

The client is to arrange for the following work (WHICH IS NOT INCLUDED FOR IN OUR QUOTATION):

- Removal of all fixtures and fitting from the treatment area(s) prior to our commencement of works on site
- Removal of all floor coverings including underlays from the treatment area(s) prior to our commencement of works on site
- Disconnection and reconnection of plumbing items within the treatment area(s)
- Disconnection and reconnection of electrical items and wiring within the treatment area(s)
- Disconnection and reconnection of radiators within the treatment area(s)
- Any required decoration including re-tiling of walls and floors
- Employment of reputable roofing contractors to inspect, report and repair any faults with the roof coverings, gutters and downpipes
- Employment of a reputable builder to inspect, report and repair the following noted items below:
- Cleaning of work area(s) and areas leading up to the work area(s). Our operatives will take steps to minimise dust invasion out with the areas of work(s)
- Supply water, power and light
- Exterior drainage to be maintained in order to allow water to flow freely
- Note: the system installed by Wise will control the environment as far as providing a dry floor or dry surface(s) depending on options taken. However, others will need to design effect effective heating and ventilation so that water vapur caused by occupation does not encourage condensation

Any defects as noted within 'External Observations' will need to be rectified by the client under a separate contract.

Upon completion of the contract and the account being paid in full our guarantee (if applicable) will be issued, offering you peace of mind by protecting your property for the future.

Where a guarantee is issued by Wise Property Care Ltd it will be conditional upon any building defects being corrected and the building being maintained in a weather tight and waterproof condition.

Completion of the contract to your satisfaction will be identified by either a signature on our operative's worksheet when works have been completed, or by means of a telephone call from our Sales Ledger Department.

In order to comply with Health & Safety Regulations regarding the use of our chemicals it is essential that the areas of treatment remain vacant and well ventilated during and for a minimum of 1 hour after treatment.

CLIENT NOTE

If we receive your instructions to inspect the concealed structural timbers our surveyor will provide a quotation for the required exposure works based on the owner/others removing or setting aside floor coverings/furniture. No allowance is normally made for making good or decorating areas exposed for access. This work should be carried out by the owner/purchaser of the property at their own cost. Wise Property Care Ltd accept no responsibility for the condition of the concealed structural timbers should you decide to proceed without this recommended inspection.

Our inspection was not and should not be relied upon as a substitute for a structural survey. We have not investigated, considered or reported upon any other matter including, without limitations, timbers exposed to the outside or timbers not visible at the time of inspection. However, should you proceed on the present basis; we shall advise you of any other infestation or fungal infection we discover during execution of the works (if any) and advise/quote accordingly.

It may be seen from our specification that we may have included for the removal of the existing plaster. In removing plaster it is not unusual for dust to find its way to the remotest parts of the property. We will take the precaution to minimise this nuisance wherever practical within the immediate area of our work but we respectfully suggest that you should also take some precautions to protect furniture and the like elsewhere in the property. We regret we can take no responsibility for cleaning or for any damage that may be caused by dust, however if you wish us to include for industrial cleaners to visit the property on completion of our works, we can do so.

During our inspection, we carried out an assessment of potential hazards and health risks, which might arise during the course of our works. These were done under the COSHH (Control of Substances Hazardous to Health) regulations 1989. We noted that the property was unoccupied at the time of our inspection and have assumed that it will be occupied when we carry out our works. When you ask us to carry out these works, please let us know if there are any changes in this assumption, or if there are any other material changes when we start work, we can forward a copy of our assessment to you.

The nature of remedial construction works is such that, occasionally, the problem outlined is more extensive than anticipated. Therefore any timescales discussed for the project are indicative only, as extra works may be required. Whilst we make every effort to minimise inconvenience to our customers, we may not, because of other commitments, be able to continue with the extra works immediately. If this is the case, we will schedule the extra works as soon as we possibly can, but cannot be held responsible for difficulties this may cause.

As a company we carry out the following:

- Dry Rot Eradication
- Wet Rot Eradication
- Woodworm Eradication
- Rising Damp control
- Penetrating Damp Control
- Condensation Control
- Basement Tanking (Water management systems)
- Invasive Weed Control (Japanese Knotweed, etc)
- Structural Repairs (Crack stitching, wall stabilisation)

QUOTATION

The cost of our recommended treatment and associated works (if applicable) is shown within the quotation below. on the attached form and is based on the assumption that the work can be carried out in one continuous operation.

Our quotation covers only those items specifically stated in the report to be under taken by Wise Property Care Ltd. All other repairs and/or ancillary works are to be the responsibility of others under separate contract.

Our quotation is issued subject to it being accepted in writing within a period of 28 days, with the work proceeding within three months of acceptance.

Please complete the enclosed acceptance of quotation and return it to this office where our contracts coordinator Maureen Cantley will contact you to arrange a mutually convenient commencement date to carry out the works as detailed in our report.

Alternatively you can contact us at our Edinburgh office during office hours on 0131 603 6189 or by e-mail at maureen.cantley@wisepropertycare.com

This report is copyright and is for the above addressee only; we can accept no responsibility for our survey, or this report towards any other person or persons. On no account must it be duplicated or copied in whole or part without the authority of a company director of Wise Property Care Ltd.

YOUR SURVEYOR AND HOW TO CONTACT US

The surveyor who has been dealing with this property is William Mulgrew and can be contacted on mobile number 07957821913. Alternatively, you can also reach William Mulgrew using the branch details at the front of the report or contact him by email at William.Mulgrew@wisepropertycare.com.

Yours faithfully,

William Mulgrew

Senior Managing Surveyor

t: 07957821913

Edinburgh

Head Office

8 Muriel St

Barrhead

Glasgow

G78 1QB

t: 0131 516 8869

e: east@wisepropertycare.com

0131 603 6189

Quotation



Client Name	Mr Cran	Mr Cran	
Company Name	Drummon	Drummond Miller LLP	
Client Property Address	9 Joppa Road EDINBURGH Midlothian EH15 2HA		
Date	16/07/202	4	
ID	ENQ7752	09	
Description	Total Excl VAT	VAT Amount	Total Incl VAT
Carry out Damp Proofing Works and Membrane Istallation including Electrical, Plumbing and Plastering	£3,584.00	£716.80	£4,300.80
Are you going to be the end user of the services on this agree Are you VAT registered? [NO / YES]	ement? [NO / YES]	Are you CIS registered VAT Number:	
Terms and Conditions apply. I understand the observations and recommendations contained in this report and confirm that they correspond with my instructions to request an esfor remedial work required in relation to the property. I fully understand and accept the terms of the transferable guarantee, where applicable, which applies in relation to the areas of the property where remediation work has been identified as being required in the report. I accept that the propose remediation work does not include carpeting, the moving of furniture, removal of fixtures and fittings, painting, electrical or plumbing work unless this been specifically provided for in the quotation. I confirm that neither a full exploratory examination nor disruptive exposure has been carried out.			
Surveyor Signature:	Customer Sig	nature:	

Please return this completed form to the above Branch Office address.

WISE PROPERTY CARE STANDARD TERMS AND CONDITIONS

THESE TERMS

- 1.1 These are the terms and conditions on which we undertake any works identified in our survey report which you ask us to carry out.
- 1.2 In particular your attention is drawn to paragraph 5 which relates to the price payable, paragraphs 8 and 9 which set out your rights to cancel this contract, paragraph 12 which sets out the limit of our liability to you and paragraph 13 which sets out how we may use your personal information.

2. INFORMATION ABOUT US AND HOW TO CONTACT US

- 2.1 We are Wise Property Care Limited, a company registered in Scotland. Our company registration number is SC168153 and our registered office is at 8 Muriel Street, Barrhead, Glasgow G78 1QB. Our registered VAT number is 671742426.
- 2.2 You can contact us by telephoning our customer service team on the number set out on our quotation or by writing to us at the address on the same form.
- 2.3 "Writing" includes emails. When we use the words "writing" or "written" in these terms, this includes emails.
- 2.4 "Works" includes any works or treatments we provide to you as set out in our survey report and could include some materials and or goods needed to complete those Works.

OUR CONTRACT WITH YOU

- 3.1 Following your enquiry to us, we may decide to send a surveyor to your property to evaluate and assess your requirements. If it is critical that the Works are completed by a particular date you must advise us of this at the time of the survey. The surveyor may give you a quotation on the day as to the likely costs of the Works.
- 3.2 You may be required to pay a fee for the survey report. If this is required, you will be told at the time of your enquiry. This fee will be refunded in full should you cancel the survey or if you proceed with all the Works recommended in the survey report. However we will not refund the fee if the survey report is for a condensation control system for your property.
- 3.3 After the visit by our surveyor, we will send to you the survey report confirming our recommendations, our Works and our price.
- 3.4 The survey report will contain important information describing our Works, the information we may need from you in preparation for the Works and the actions you may need to take to help us. It will also tell you what we are not doing.
- 3.5 If at the time of receiving the survey report you have not already signed the order giving us permission to proceed with the Works, then if you would like us to perform the Works, you must confirm this in writing. Our acceptance of your order will take place when we contact you whether by email, telephone or letter to accept it, at which point a contract will come into existence. That contract will incorporate these terms and conditions.

4. CHANGES

- 4.1 If you wish to make a change to the Works, please contact us. If the change is possible, we will let you know about any changes to the price, the timing of supply or anything else which may alter as a result of your request and ask you to confirm whether you wish to go ahead with the change.
- 4.2 We may change the Works to implement minor technical adjustments and improvements. If we do this then we shall notify you of the changes and any impact on the Works, timing of supply or anything else.
- 4.3 We will not notify you if we are only substituting materials or equipment of similar quality and performance to those specified in the survey report or any other document issued to you.

5. PRICE AND PAYMENT

- 5.1 The price of the Works identified in our survey report (which includes VAT) will be the price set out in our quotation or as set out in our survey report to you.
- 5.2 Sometimes it is not possible to calculate the full price of the Works. Our survey report will clearly set out the price for the Works and materials set out in it. If additional materials or Works are required we will provide you with a new quotation setting out the price for such additional materials/Works in writing and will not proceed with any such additional work without your written acceptance.
- 5.3 If the rate of VAT changes between your order date and the date we supply the Works, we will adjust the rate of VAT that you pay, unless you have already paid for the order in full before the change in the rate of VAT takes effect.

- 5.4 We shall require payment in full before we commence the Works or, where appropriate, a deposit. The balance shall be due to us immediately on completion of the Works and on receipt of such payment we shall issue to you an invoice for the whole value of the Works.
- 5.5 If you do not make payment to us on completion of the Works we may charge you interest on the overdue amount at the rate of 4% a year above the base lending rate of HSBC PLC from time to time. This interest shall accrue on a daily basis from the due date until the date of actual payment of the overdue amount, whether before or after judgment. You must pay us interest together with any overdue amount.
- 5.6 If you have any queries regarding the payment then please contact us promptly explaining why you think it is wrong and we will not charge you interest until we have resolved the issue

6. PROVIDING THE WORKS

- 6.1 We will begin the Works on the date agreed with you at the time of the survey or following your acceptance of the Works set out in the survey report. We will let you know before the start of the Works the estimated completion date.
- 6.2 We may need certain information from you or we may require you to carry out certain actions so that we can carry out the Works, for example, clearing rooms or emptying cupboards. If we require your assistance, this will be stated in the survey report.
- 6.3 We will contact you to ask for this information or for you to confirm that you have carried out the actions. If you do not give us this information, or if you give us incomplete or incorrect information or if you have not carried out your actions, we may either end the contract or make an additional charge of a reasonable sum to compensate us for any extra work that is required as a result. We will not be responsible for completing Works late or not supplying any part of them if this is caused by you not giving us the information or failing to carry out the actions within a reasonable time of us asking.
- 6.4 As our access to all parts of your property may have been limited or restricted during our survey, if when we start providing the Works, we discover that the problem is more extensive than we originally thought then we reserve the right to provide a quote to you for this additional work.
- 6.5 If our completion of the Works is delayed by an event outside our control (including for example unavailability of service staff due to illness) then we will let you know as soon as possible and we will take steps to minimise the effect of the delay. Provided we do this we will not be liable for delays caused by the event, but if there is a risk of substantial delay you may contact us to end the contract and receive a refund for any Works you have paid for but not received.
- 6.6 If you do not allow us access to your property to perform the works as arranged (and you do not have a good reason for this) we may charge you additional costs incurred by us as a result. If, despite our reasonable efforts, we are unable to contact you or re-arrange access to your property we may end the contract and paragraph 10.2 will apply.
- 6.7 If we are unable to complete the Works on the date we originally advised to you, unless this is due to circumstances outside our control, then you may end the contract but only if you have told us in writing before we accepted your order that the Works had to be completed by that date.
- 6.8 If you do not wish to end the contract, you can give us a new deadline to complete the Works, which must be reasonable, and if we do not meet this new deadline you can also end the contract.
- 6.9 If you do choose to end the contract under paragraphs 6.7 or 6.8 you can cancel your order for any Works only partially completed but we will invoice you for those partially completed Works at the date you have ended the contract.

7. GUARANTEES

Where the survey report states that our Works come with a guarantee, we shall issue to you the guarantee upon receipt of payment in full. The terms of the Guarantee are shown on the relevant certificate of Guarantee

8. CANCELLATION RIGHTS

- 8.1 If you end the contract for a reason set out at (a) to (e) below the contract will end immediately. The reasons are:
 - (a) we have told you about an upcoming change to the Works or these terms which you do not accept;
 - (b) we have told you about an error in the price or description of the Works you have ordered and you do not wish to proceed;

WISE PROPERTY CARE STANDARD TERMS AND CONDITIONS

- (c) there is a risk that the supply of the Works may be significantly delayed because of events outside our control:
- (d) we have or we wish to suspend the supply of the Works for technical reasons (for example due to the presence of asbestos or bats), in each case for a period of more than twenty-eight days or until we get the appropriate statutory consent. whichever is the later: or
- consent, whichever is the later; or

 (e) you have a legal right to end the contract because of something we have done wrong including because we will be unable to complete the Works by the date you specified when you confirmed your acceptance under paragraph 3.5.
- 8.2 To end the contract, please contact the local service office on the telephone number or e-mail address set out in the quotation. Please provide your name, home address, details of the order and, where available, your phone number and email address.
- 8.3 We will refund to you the price you paid for the Works not yet provided, by the method you used for payment. However, we may make deductions from the price (or, if you have not made an advance payment, charge you) the reasonable costs we will incur as a result of you ending the contract.

9. STATUTORY RIGHTS TO CANCEL

THIS PARAGRAPH 9 ONLY APPLIES IF YOU ARE A CONSUMER AND YOU HAVE ENTERED INTO A DISTANCE OR OFF-PREMISES CONTRACT.

- 9.1 If this applies, then under the Consumer Contracts (Information, Cancellation and Additional Charges) Regulations 2013 you have a legal right to change your mind within 14 days.
- 9.2 Because you have this legal right to change your mind, we will not provide the Works to you until after the 14 day period has expired (the "Cooling off period").
- 9.3 If you believe the Works are urgent and you would like us to commence the Works during the Cooling off period then you must sign a waiver giving us permission to start early.
- 9.4 You must realise that by giving us permission during the Cooling off period you may lose your right to cancel and this will mean that:
 - (a) if we have completed the Works in full you cannot change your mind, even if the 14 day Cooling off period is still running; or
 - (b) if you cancel after we have started the Works but before the Works are completed during the Cooling off period, you must pay us for the Works to the extent completed at the time you tell us that you have changed your mind.
- 9.5 If you are ending within 14 days of signing the contract under paragraph 9.2, please complete the cancellation form at the end of the order form or contact us on the number set out in the quotation

10. Our rights to end the contract

- 10.1 We may end the contract for works at any time by writing to you if:

 (a) you do not make any payment to us when it is due and you
 - (a) you do not make any payment to us when it is due and you still do not make payment within seven days of us reminding you;
 - (b) you do not, within a reasonable time of us asking, provide information we require or carry the actions that are necessary for us to provide the Works; or
 - you do not, within a reasonable time, allow us access to your premises.
- 10.2 If we end the contract in the situations set out in paragraph 10.1 we will refund any money you have paid in advance for the Works we have not provided but we may deduct or charge you reasonable compensation for the net costs we will incur as a result of your breaking the contract.

11. IF THERE IS A PROBLEM WITH THE WORKS

- 11.1 If you have any concerns or complaints about the Works, you can contact us in accordance with our complaints procedure which can be requested by telephoning our customer service team on the number set out on our quotation or by writing to us at the address on the same form.
- 11.2 If you believe there is a fault or problem with the Works we have provided, then you must contact us promptly so that we have an opportunity to fix the problem. If you fail to give this opportunity and instead use another company then any additional charges or losses you have suffered will not be recoverable from us.
- 11.3 If you have not contacted us with any complaint within 6 months of completion of the Works we will be entitled to assume that the Works were performed satisfactorily.

2. OUR LIABILITY FOR LOSS OR DAMAGE SUFFERED BY YOU

- 12.1 If we fail to comply with these terms, we are responsible for loss or damage you suffer that is a foreseeable result of our breaking this contract or our failing to use reasonable care and skill, but we are not responsible for any loss or damage that is not foreseeable.
- 12.2 If we are undertaking Works in your property, we will make good any damage to your property caused by us but our total liability to you arising from the damage will be limited to twenty thousand pounds (£20,000). We shall not in any circumstances be liable for any (a) costs of repairing any pre-existing faults or damage to your property that we discover while providing the Works; (b) loss of profits, economic or financial loss, loss of sale or business, loss of use or business interruption, loss of goodwill; or (c) indirect or consequential loss.
- 12.3 Nothing in this paragraph 12 or elsewhere in this contract excludes or limits our liability for death or personal injury caused by our negligence; for fraud or fraudulent misrepresentation; or to the extent such liability may not be excluded or limited at law.

13. How we may use your personal information

- 13.1 We shall process your personal data, including sending you marketing information, in accordance with applicable data protection legislation and our privacy notice which is located at: https://www.rentokil-initial.com/site-services/cookie-and-privacy-policy/privacy-policy.aspx.
- 13.2 If you do not wish to receive marketing information from us you can opt out here: opt-out@wisepropertycare.com. We will continue to send you communications as necessary for the performance of the contract and/or the services we are providing to you.

14. OTHER IMPORTANT TERMS

- 14.1 We may transfer our rights and obligations under these terms to another organisation.
- 14.2 You may only transfer your rights or your obligations under these terms to another person if we agree to this in writing. However, you may transfer our guarantee at paragraph 7.1 to a person who has acquired your property. We may require the person to whom the guarantee is transferred to provide reasonable evidence that they are now the owner of the property.
- 14.3 This contract is between you and us. No other person shall have rights to enforce the terms.
- 14.4 Each of the paragraphs of these terms operates separately. If any court or relevant authority decides that any of them are unlawful, the remaining paragraphs will remain in full force and effect.
- 14.5 If we do not insist immediately that you do anything you are required to do under these terms, or if we delay in taking steps against you in respect of your breaking this contract, that will not mean that you do not have to do those things and it will not prevent us taking steps against you at a later date.
- 14.6 The parties shall comply with laws relating to this agreement and the Works. Each party shall promptly report to the other party any request or demand for any undue financial or other advantage in connection with this agreement.
- 14.7 Other than payment for the Works, neither party shall be liable for any failure or delay which is caused by circumstances beyond its reasonable control. If the circumstances continue for more than 30 days, either party may terminate this agreement by giving notice.
- 14.8 These terms are governed by Scottish law and legal proceedings will be in the Scottish courts.

EXPRESS REQUEST TO COMMENCE THE DELIVERY OF WORKS EARLY

I hereby request the immediate performance of the works and acknowledge that I will lose my right of withdrawal from the contract once the works are fully performed. I also understand that if I cancel and the works are part complete I will be liable to pay for any works up to the date I cancelled.

Please commence the works within the Cooling off Period

Signed
Date



What makes us great?



Recognised by Which?

1st Scottish Preservation Company to be endorsed and recognised by Which? Visit trustedtraders.which.co.uk to see what makes a trader with this status so special.

Average Rating



Rated and Recommended

Average 4.5 star rating online. In addition, our customer questionaires show that 96% of customers would recommend us

PCA (wards)

Award Winning Contractors

Property Care Association Award Winners in 2014 and commended in 2011. Also awarded 'Best Business Turnaround' and recent finalist in both 'The Entrepreneur of the Year' and 'Chamber of Commerce Business Awards'





40 Years Experience - Scottish Based

40 years experience in building preservation serving Scotland with local branches Scotland wide. Scotlish company...local service.

Our Professional Memberships and Accreditations















For more information about our professional memberships, watch our video at:

wisepropertycare.com/approvedcontractor

Specifications

The company reserves the right to change these specifications at any time without notice, subject to changes in technique, improvement in materials or in particular cases where a change might be found necessary, during the course of the work.

1. Woodworm

The purpose is to treat as many available surfaces of the infected timber as possible. The treatment in this section covers infestation by Common Furniture Beetle Anobium Punctatum, Death Watch Beetle Xesobium Rufovillosum and Powder Post Beetle Lyctus Sps. In cases of infestation by House Longthorn Beetle Hylotrupes Bajulus, these treatments are supplemented as follows: After cleaning, cut away heavily decayed sapwood, reinforce or renew any timbers whose structural strength is seriously impaired.

A Roof Void Treatment

Clean down as deemed necessary all exposed roof timbers. Apply insecticide to all exposed surfaces of all the timbers

B Floor Treatment

Lift sufficient floor boards. Apply insecticide to all exposed surfaces. Re-lay existing floor boards renewing where specified in our report.

C Joinery and Timber Treatment

Form holes to 2/3 of the depth of the infested timber in the least conspicuous position, to supplement existing flight holes. Apply insecticide to all accessible unpainted surfaces of the timber. This treatment may be supplemented by recommendations in our report.

D Staircase Treatment

Apply insecticide to all exposed timber surfaces. Joinery timber treatment may also be specified for wall strings and other timbers whose reverse sides are not accessible.

2. Wet Rot

- A Remove any timber that our surveyor has deemed seriously weakened or unsightly. Remove from the area, debris resulting from our work.
- B Replace with sound timber, any timbers removed in paragraph (a). All such timber to be pretreated or treated on site

3. Dry Rot

The true dry rot fungus Serpula Lacrymans attacks the timber under conditions of damp and inadequate ventilation. It forms special water conducting strands, which enable it to travel rapidly, penetrating most building material and attacking timber from the original source of decay. Small portions of the fungus left untreated in timber or wall areas are capable of developing independently, and it is therefore essential that the fullest extent of any attack be determined and subsequently treated. Our report will, as far as possible, outline the extent of the attack and specify the appropriate sections of the following treatments. See also section 4.

- A Cut away all timbers as specified in our report, and remove from the premises
- **B** Remove plaster and rendering coats as specified above
- C Clean all exposed walls and other surfaces to remove surface mycelium of the fungus. Drill holes at staggered centres in a band around the perimeter of the exposed area to a depth of 1/3 to 2/3 of the wall thickness.

Irrigate each hole and apply fungicide to all surfaces specified in our report.

- D Apply fungicide liberally to all timber surfaces as specified
- E Replace any timbers that have been removed with sound timber, either pre-treated or treated with fungicide on site. Joist ends to be treated with fungicidal paste and in very damp conditions to be capoed with damp proof material.
- **F** Re-render all previously rendered surfaces according to our plastering specification.
- G Provide and fix new air bricks, as specified in our report.
- **H** Drill and irrigate around perimeter of door and window openings within the dry rot area.

4. Fungal Decay (Special Note)

In respect of attacks by both wet and dry rot fungi, our report will, where possible, determine the source of the dampness and specify any other repairs that may be necessary to remedy it. One of the most important measures in the remedy of fungal decay is the reinstatement and maintenance of dry conditions which, in some instances, would be adequate to ensure its eventual eradication. Treatment is required to hasten this process, to replace decayed timber, and to protect elements of the building at risk. However, it is vital that the measure taken to ensure dry conditions be perpetrated thereafter and this is an essential condition of our guarantee.

5. Chemical Damp-proof Course

The insertion of a chemical damp-proof course is recommended for most types of walling, and involves the injection of chemical under pressure into holes drilled at intervals into the wall, at levels decided where practicable, by our surveyor at the time of his inspection.

- A Drill 9mm to 16mm holes 75mm to 225mm apart into the masonry at the level to be damp proofed as directed by our surveyor.
- B Irrigate each hole under pressure with chemical solution ensuring even distribution.
 C Make good external holes with sand cement mortar or mastic.
- D Cavity walls may be drilled and injected either from one side only or from both sides, depending upon the circumstances surrounding the operation.
- E All skirtings and fittings will either be renewed by our operators or by our client's builder, as specified in our surveyor's report

NOTE: In certain circumstances we recommend the transfusion process for chemical dampproofing. This specification is available when required.

6. Injection Creams

- A 12mm diameter holes drilled horizontally into the mortar joint at 120mm centres and to a depth of 10-20mm from the opposite face.
- B Fill boreholes with injection cream using a low pressure sprayer or cartridge gun.

7. Electro Osmotic Damp-proof Course

- **A** Drill 14mm holes to a depth of approximately 100mm, 925mm apart into a mortar joint at a level determined by our surveyor.
- B Insert anodes, fill with cement and clip titanium wire into mortar joint.
- C Fix power unit and connect to 13 amp unswitched socket.
- **D** Drive standard earth rod into ground at least 2 metres from the nearest anode so that the top is lower than any of the wall anodes.
- E Fix one end of the earth wire to the earth rod and make waterproof. Fix the other end to the power box. Switch on mains power and the light emitting diode will illuminate. The system is then working.
- F Skirtings and architraves will either be fitted or renewed by our operators or the client's builder, as specified in our surveyor's report.

8. Plastering

A Whenever dampness arises in a wall, certain contaminants, either acidic or alkaline are introduced into the wall.

This contamination will migrate to this surface as the wall dries, leaving a crystalline efflorescence. These deposits can absorb and retain moisture from the air and the walls thus tend to become damp, particularly during humid conditions. This dampness usually occurs where the wall has been replastered after the installation of a damp proof course and is often confused with rising damp. It is because of this that correct replastering is of paramount importance to ensure a dry wall

- **B** Wherever rising damp has contaminated plaster, that plaster must be removed to an area 300mm beyond the damp staining. This need not be done when the damp course is inserted.
- C The wall should be replastered using Limelite Renovating Plaster to manufacturers specification as stated in British Board of Agrément Certificate.

UNDER NO CIRCUMSTANCES SHOULD ANY OTHER PREMIX PLASTER BE USED

- D The bottom edge should be stopped 25mm from the floor. Great care should be taken to ensure that all plaster droppings are removed and are not left behind the skirtings.
- E All skirtings and fixings should be treated with fungicide prior to fixing.
- F The floor to wall joint should be sealed with a waterproof compound to prevent the upward movement of water vapour between the wall and the floor slab or damp proof membrane in the floor slab. This waterproof coating should extend 100mm up the wall and 50mm across the floor slab (applies only to solid floors).

Client Information

THE FOLLOWING HELPFUL INFORMATION SHOULD BE READ IN CONJUNCTION WITH OUR REPORT AND QUOTATION. IT IS AN INTEGRAL PART OF OUR REPORT AND QUOTATION. WHERE ADVICE IS GIVEN TO CLIENTS, IT SHOULD BE ACTED UPON IN THE TIME SCALE SHOWN. IF THIS IS NOT POSSIBLE WISE PROPERTY CARE SHOULD BE NOTIFIED IN WRITING IMMEDIATELY.

GENERAL TO ALL SERVICES CARRIED OUT BY WISE PROPERTY CARE

- 1 The client should ensure that mains water and electricity are available at all times whilst Wise Property Care are on site.
- 2 The Wise Property Care Quotation is based on, unless reported differently, the client being responsible for ensuring that all furniture, floor coverings and other household possessions, including plants, are removed from the treatment area prior to the commencement of the work and subsequently replaced. It is not recommended that floor coverings of any type be replaced for at least five days, or as recommended by the manufacturer, whichever is the language.
- 3 Wise Property Care cannot accept any responsibility for any damage to hidden services not previously brought to their attention by the client.
- 4 Where Wise Property Care have included for the removal and replacement of any electrical, gas or water service to facilitate their work, they do so on the basis that the respective services are without defect. At the time of replacing a service any apparent defect which prevents Wise Property Care from effectively doing so will be brought to the clients attention. If additional work is necessary, a supplementary report and Quotation will be submitted.
- 5 Party walls are the joint responsibility of adjoining owners. Where work on a party wall is necessary the client must advise the owner of the adjoining property beforehand.
- 6 Where work to an external wall is to be carried out from the neighbours property, it is the responsibility of the client to obtain written permission beforehand and to ensure free working access at all times.
- 7 When working on the outside of the property Wise Property Care will take every care of plants and shrubs adjacent to the external working area but cannot accept any responsibility for damage.
- 8 Wise Property Care reserves the right to change or vary its recommendations from time to time, without notice, in order that the customer may obtain the benefits of either improved techniques, better materials or improved working methods.
- 9 With regards to the area specified for treatment, care should be taken by the client to ensure that the building is maintained in a waterproof and weatherproof condition, prior to, during and after treatment by our Operatives. Roof coverings should not be removed until such time as treated timbers are touch dry. Treated timbers and masonry should not be exposed to weather penetration which will negate the effectiveness of any treatment and invalidate the quarantee.



Certificate of Guarantee

Client		Contract No.		
Assignee		Report Date		
Propert	ty	Date Treatment		
		Completed		
A		ient in respect of work carried out by Wise Property Care Ltd. Henceforth y in accordance with the above mentioned report, estimate and contract.		
В	infestation by wood boring insect or attack by a	e date that the contract was complete that any continuation or recurrence of wood rotting fungus in any of the timbers treated against such decay will be ment as may be necessary, excluding redecoration.		
C		the report fail to prevent the rise of dampness from the earth into the walls econtract was completed, WPC guarantees to repair the failure free of		
D	reports (and sketches where applicable) are pro investigation charge (this charge will be refunde	parantee, it is essential that this guarantee certificate and all of the original by decided by the claimant, to the company, together with the then appropriate of in full if any treatment covered by clause B and C above has failed, lure to provide the aforementioned documents and/or fee will invalidate this		
E	disposal systems, domestic plumbing, adequate sub-floor ventilation and gen (ii) Where recommendations given by WP (iii) Where, subsequent to the completion of	in a good and proper state of maintenance including rainwater goods and internal and external ground levels relative to the damp proof course, neral structure of the property.		
F	This Guarantee does not extend to furniture and	doors.		
G	The rights conferred upon the client by this docu	ument shall be in addition to any rights the client may have at Common Law.		
Н	by the client named above to the new owner pro the new owner shall have (i) Given written notice of the change to W (ii) Permitted WPC's representative to insp (iii) Paid WPC's then current transfer and ir (iv) This Guarantee is conditional upon WP	pect the property to ensure that all conditions have been complied with.		
		For all guarantee enquires, contact our Head Office at:		
_	and on behalf of Wise Property Care	8 Muriel Street, Barrhead, Glasgow G78 1QB T: 0141 876 9200 F: 0141 876 9900 E: headoffice@wisepropertycare.com		
Date		Alternatively, find your local branch details at wisepropertycare.com/branches		



- ✓ PCA Approved
- ✓ Provides cover where contractor ceases to trade
- ✓ Provides access to Financial Ombudsman Service
- ✓ Individual insurance certificates for multiple properties
- ✓ GPI is a member of the Financial Services Compensation Scheme
- ✓ Automatic free assignment on sale of property
- ✓ GPI is a UK authorised and regulated insurance company

wisepropertycare.com/gpi 0800 65 22 678



The Wise Choice?

Scotland's Leading Provider of Property Care Services

Wise Property Care has grown dynamically over the last decade by providing high quality and technologically advanced services. Wise Property Care has become the professional's first choice for in-depth low disturbance investigations and sympathetic remediation regimes.

Privately Owned and Local

While Wise Property Care is a national company, it continues to be owned and operated by Scottish experts for Scottish property owners. Wise Property Care operates on the principle of providing services that the owners would themselves expect to experience and is proud of its local coverage and quality of service.

True Value for Money

"It is unwise to pay too much, but it is unwise to pay too little. The common law of business balance prohibits paying a little and getting a lot. It cannot be done. If you deal with the lowest bidder, it is well to add something for the risk you run."

John Ruskin (1819 – 1900)

We offer Value for money without compromising quality of work or materials.

Local Coverage

Wise Property Care realise the importance of employing local people who have the benefit of local knowledge and the ability to serve an area promptly. Regional offices in Glasgow, Edinburgh, Falkirk, Kinross, Dunfermline, Aberdeen, Hawick and Ayrshire support our countrywide surveying staff.

Minimum Disruption to Your Life

In recent years there have been substantial advances in the products used to treat preservation problems. So much so, that in the majority of cases, it is possible to re-enter a treated area after 1 hour. Today, all products are water rather than solvent based meaning there are now no offensive odours. These innovations translate into reduced disruption to the lives of our customers and clients can be assured that it is safe to have preservation work carried out. Wise Property Care wish to reduce inconvenience as much as possible and can discuss any special requirements with individual home owners.

Award Winners

Wise Property Care's performance is reflected in awards bestowed upon the company by independent organisations. In recent years, the company has been awarded 'Best Business Turnaround' at the National Business Awards of Scotland 2001: been 'Commended for Innovation'



by the 'Property Care Association' and has been named as a finalist in the 'Entrepreneur of the Year' awards, 'Chamber of Commerce Business Awards' and the 'IOD Scotland Director of the Year Awards'

Guaranteed Peace of Mind

Wise Property Care is a member of the Property Care Association (PCA), helping to build best practice within the industry. The company is also a member of 'Guarantee Protection Insurance', an independent organisation which offers insurance-backed guarantees in addition to the Wise Property Care 20 year company guarantee. Wise Property Care is actively involved in ensuring the highest industry standards to the extent that since 1997, Les Meikle (MD) has been chairman of the Scottish Region of the PCA and is currently the Deputy Chairman of the PCA in the UK.

Assured Quality

Wise Property Care is an approved ISO 9001: 2000 and ISO 14001 registered firm demonstrating our commitment to quality in company administration systems.



shepherd.co.uk





Home Report Valuation Report Mortgage & Re-Mortgage Valuation **Executory Valuation Inheritance Tax Valuation Tax Valuation** Separation Valuation **Private Sale Valuation**

New Build, Development & Plot Valuation

Extension & Alteration Valuation Insurance Reinstatement Valuation

> **Portfolio Valuation Rental Valuation Driveby Valuation Desktop Valuation**

Energy Performance Certificate (EPC) Level Two Survey & Valuation Report Level Two Condition Report Expert Witness Report Council Tax Appeal





Commercial Valuation Commercial Agency Acquisitions & Disposals Commercial Lease Advisory Rent Reviews Asset Management Project Consultancy Development Appraisals Rating Commercial Property Auctions Property Management Professional Services Licensed Trade / Leisure



PROPERTY & CONSTRUCTION CONSULTANTS



Quantity Surveying Building Surveying Project Management Dispute Resolution Support Services Principal Designer Clerk of Works **Commercial EPC Fire Engineering Health & Safety Management Employer's Agent Energy Department Housing Services Development Monitoring**

Mediation Services

Aberdeen △▲▲ 01224 202800

△▲ 01292 267987

Bearsden

Birmingham **△** 0121 270 2266

Coatbridge

Cumbernauld △▲ 01236 780000

Dalkeith △▲ 0131 663 2780 **Dumbarton**

△▲ 01389 731682

Dumfries

△▲△ 01387 264333

Dundee

△▲ 01382 200454 △ 01382 220699

Dunfermline △ 01383 731841

East Kilbride △▲ 01355 248535

Edinburgh △▲ 0131 2251234 △ 0131 557 9300

Elgin

△▲ 01343 553939

△▲ 01324 635 999

Fraserburgh △▲ 01346 517456

Galashiels △▲ 01896 750150

Glasgow △△△ 0141 331 2807

Glasgow South △▲ 0141 649 8020

Glasgow West End

Greenock △△01475 730717

Hamilton

△△01698 897548

Inverness △△△01463 712239

Kilmarnock △△01563 520318

Kirkcaldy △ <u>△</u> 01592 205442

Leeds △ 0113 322 5069

Livingston △ ▲ 01506 416777

London ▲△ 02033 761 236

Montrose △▲ 01674 676768

Motherwell △ △ 01698 252229

Musselburgh △ △ 0131 653 3456

△▲ 01631 707 800

Paisley △ ▲ 0141 889 8334

△▲ 01738 638188 △ 01738 631631

Peterhead △△ 01779 470766

St Andrews △▲ 01334 477773 △ 01334 476469

Saltcoats △▲ 01294 464228

Stirling △△ 01786 450438 △ 01786 474476