1F1 15 WARRISTON DRIVE WARRISTON EDINBURGH EH3 5LY



## **Home Report**

shepherd.co.uk



**CHARTERED SURVEYORS** 

All Angles Covered

Residential | Commercial | Property & Construction



Energy Performance Certificate



### **Energy Performance Certificate (EPC)**

## Scotland

Dwellings

#### 1F1, 15 WARRISTON DRIVE, WARRISTON, EDINBURGH, EH3 5LY

| Dwelling type:            | Mid-floor flat               |
|---------------------------|------------------------------|
| Date of assessment:       | 15 April 2025                |
| Date of certificate:      | 22 April 2025                |
| Total floor area:         | 72 m <sup>2</sup>            |
| Primary Energy Indicator: | 280 kWh/m <sup>2</sup> /year |

**Reference number:** Type of assessment: Approved Organisation: Main heating and fuel:


1315-2824-5100-0585-1296 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas

#### You can use this document to:


- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

| Estimated energy costs for your home for 3 years* | £3,333 | See your recommendations       |
|---|--------|--------------------------------|
| Over 3 years you could save*                      | £1,458 | report for more<br>information |

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



#### Very environmentally friendly - lower CO<sub>2</sub> emissions



#### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is band D (65). The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$ emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (61)**. The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Top actions you can take to save money and make your home more efficient

| Recommended measures                   | Indicative cost  | Typical savings over 3 years |
|--|------------------|------------------------------|
| 1 Cavity wall insulation               | £500 - £1,500    | £612.00                      |
| 2 Internal or external wall insulation | £4,000 - £14,000 | £120.00                      |
| 3 Hot water cylinder thermostat        | £200 - £400      | £123.00                      |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE **DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE** 

## 1F1 , 15 WARRISTON DRIVE, WARRISTON, EDINBURGH, EH3 5LY 22 April 2025 RRN: 1315-2824-5100-0585-1296

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element               | Description  | Energy Efficiency | Environmental  |
|-----------------------|--|-------------------|----------------|
| Walls                 | Cavity wall, as built, no insulation (assumed)<br>Solid brick, as built, no insulation (assumed) | ★★☆☆☆<br>★★☆☆☆    | ★★☆☆☆<br>★★☆☆☆ |
| Roof                  | (another dwelling above)   | —                 |                |
| Floor                 | (another dwelling below)   | —                 | _              |
| Windows               | Fully double glazed  | ★★★★☆             | <b>★★★★</b> ☆  |
| Main heating          | Boiler and radiators, mains gas  | ★★★★☆             | <b>★★★★</b> ☆  |
| Main heating controls | Programmer, TRVs and bypass  | <b>★★★☆☆</b>      | ★★★☆☆          |
| Secondary heating     | None   | —                 |                |
| Hot water             | From main system, no cylinder thermostat   | ★★☆☆☆             | ★★☆☆☆          |
| Lighting              | Low energy lighting in 78% of fixed outlets  | *****             | *****          |

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

#### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

#### The calculated emissions for your home are 49 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.5 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.8 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

## 1F1 , 15 WARRISTON DRIVE, WARRISTON, EDINBURGH, EH3 5LY 22 April 2025 RRN: 1315-2824-5100-0585-1296

| Estimated energy c | osts for this home   |                        |                          |
|--------------------|----------------------|------------------------|--------------------------|
|                    | Current energy costs | Potential energy costs | Potential future savings |
| Heating            | £2,043 over 3 years  | £1,107 over 3 years    |                          |
| Hot water          | £996 over 3 years    | £474 over 3 years      | You could                |
| Lighting           | £294 over 3 years    | £294 over 3 years      | save £1,458              |
| Totals             | £3,333               | £1,875                 | over 3 years             |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

#### **Recommendations for improvement**

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

|    |   | Indiantities and | Typical saving | Rating after | improvement |
|----|---|------------------|----------------|--------------|-------------|
| Re | commended measures                        | Indicative cost  | per year       | Energy       | Environment |
| 1  | Cavity wall insulation                    | £500 - £1,500    | £204           | C 71         | C 69        |
| 2  | Internal or external wall insulation      | £4,000 - £14,000 | £40            | C 72         | C 71        |
| 3  | Hot water cylinder thermostat             | £200 - £400      | £41            | C 73         | C 73        |
| 4  | Upgrade heating controls                  | £350 - £450      | £55            | C 75         | C 75        |
| 5  | Replace boiler with new condensing boiler | £2,200 - £3,000  | £145           | C 79         | B 81        |

#### Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- External insulation with cavity wall insulation
- Air or ground source heat pump
- Micro CHP

#### Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



#### About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

#### 1 Cavity wall insulation

Cavity wall insulation, to fill the gap between the inner and outer layers of external walls with an insulating material, reduces heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. The insulation material is pumped into the gap through small holes that are drilled into the outer walls, and the holes are made good afterwards. As specialist machinery is used to fill the cavity, a professional installation company should carry out this work, and they should carry out a thorough survey before commencing work to ensure that this type of insulation is suitable for this home and its exposure. They should also provide a guarantee for the work and handle any building standards issues. Further information about cavity wall insulation and details of local installers can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

#### 2 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long-lasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

#### 3 Cylinder thermostat

A hot water cylinder thermostat enables the boiler to switch off when the water in the cylinder reaches the required temperature; this minimises the amount of energy that is used and lowers fuel bills. The thermostat is a temperature sensor that sends a signal to the boiler when the required temperature is reached. To be fully effective it needs to be sited in the correct position and hard wired in place, so it should be installed by a competent plumber or heating engineer. Building regulations apply to this work, so it is best to check with your local authority building standards department whether a building warrant will be required.

#### 4 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

#### **5 Condensing boiler**

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

## 1F1 , 15 WARRISTON DRIVE, WARRISTON, EDINBURGH, EH3 5LY 22 April 2025 RRN: 1315-2824-5100-0585-1296

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

#### Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

| Heat demand                  | Existing dwelling | Impact of loft<br>insulation | Impact of cavity wall insulation | Impact of solid wall<br>insulation |
|------------------------------|-------------------|------------------------------|----------------------------------|------------------------------------|
| Space heating (kWh per year) | 5,630             | N/A                          | (2,233)                          | (440)                              |
| Water heating (kWh per year) | 3,225             |                              |                                  |                                    |

#### Addendum

#### About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

| Assessor's name:<br>Assessor membership number: | Mr. Darren Lewis<br>EES/016141 |
|---|--------------------------------|
| Company name/trading name:                      | J & E Shepherd                 |
| Address:  | 12 Atholl Crescent             |
|   | Edinburgh                      |
|   | EH3 8HĂ                        |
| Phone number:                                   | 0131 225 1234                  |
| Email address:                                  | edinburgh@shepherd.co.uk       |
| Related party disclosure:                       | No related party               |

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

## 1F1 , 15 WARRISTON DRIVE, WARRISTON, EDINBURGH, EH3 5LY 22 April 2025 RRN: 1315-2824-5100-0585-1296

#### Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.







## Scottish Single Survey



### survey report on:

| Property address | 1F1<br>15 WARRISTON DRIVE<br>WARRISTON<br>EDINBURGH<br>EH3 5LY |
|------------------|--|
|------------------|--|

| Customer         Lesley Scarles & Stuart Scarles |
|--|
|--|

| Customer address | 1F1<br>15 Warriston Drive<br>Warriston<br>Edinburgh<br>EH3 5LY |
|------------------|--|
|------------------|--|

| Prepared by J & E Shepherd |
|----------------------------|
|----------------------------|

| Date of inspection | 15th April 2025 |
|--------------------|-----------------|
|--------------------|-----------------|



#### PART 1 - GENERAL

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### **1.2 THE REPORT**

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### **1.4 GENERIC MORTGAGE VALUATION REPORT**

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report<sup>2</sup> will be from information contained in the Report and the generic Mortgage Valuation Report.

<sup>&</sup>lt;sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### **1.10 DEFINITIONS**

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### **PART 2 - DESCRIPTION OF THE REPORT**

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1. <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. <u>Category 2:</u> Repairs or replacement requiring future attention, but estimates are still advised.
- 3. <u>Category 1:</u> No immediate action or repair is needed.

#### WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

| Description                    | The subjects comprise a purpose built first floor flat within a three storey block.   |
|--------------------------------|---|
| Accommodation                  | First Floor: Entrance hall, living room with balcony off, two bedrooms and shower room with wc.   |
| Gross internal floor area (m²) | 72m2 approx.  |
| Neighbourhood and location     | The subjects are situated within an established residential area of<br>mixed style properties lying within the Warriston area of Edinburgh<br>and convenient for local shopping, educational and social facilities. |
| Age                            | 1960 approx.  |
| Weather                        | Dry and sunny.  |
| Chimney stacks                 | Visually inspected with the aid of binoculars where appropriate.  |
|                                | Rendered masonry type chimney stacks present.   |
| Roofing including roof space   | Sloping roofs were visually inspected with the aid of binoculars where appropriate.   |
|                                | Flat roofs were visually inspected from vantage points within<br>the property and where safe and reasonable to do so from a<br>3m ladder externally.  |
|                                | Roof spaces were visually inspected and were entered where<br>there was safe and reasonable access, normally defined as<br>being from a 3m ladder within the property.  |
|                                | If this is not possible, then physical access to the roof space<br>may be taken by other means if the Surveyor deems it safe and<br>reasonable to do so.  |

|                                     | The roof if pitched and tiled.  |  |
|-------------------------------------|---|--|
|                                     |   |  |
| Rainwater fittings                  | Visually inspected with the aid of binoculars where appropriate.  |  |
|                                     | Cast iron gutters and downpipes.  |  |
|                                     |   |  |
| Main walls                          | Visually inspected with the aid of binoculars where appropriate.  |  |
|                                     | Foundations and concealed parts were not exposed or inspected.  |  |
|                                     | The main walls are built of traditional cavity brickwork with render and pointed brick finishes.                                |  |
|                                     |   |  |
| Windows, external doors and joinery | Internal and external doors were opened and closed where keys were available.   |  |
|                                     | Random windows were opened and closed where possible.   |  |
|                                     | Doors and windows were not forced open.   |  |
|                                     | The windows throughout are of a UPVC double glazed type. The access door to block is of a timber variety. Timber exposed rafter |  |

| External decorations | Visually inspected.       |
|----------------------|---------------------------|
|                      | UPVC finishes to windows. |

feet are present at eaves level.

| Conservatories / porches | None. |
|--------------------------|-------|
|                          |       |

| Communal areas | Circulation areas visually inspected.                 |
|----------------|---|
|                | The communal access stair is of a solid masonry type. |

| Garages and permanent outbuildings | None.   |
|------------------------------------|---|
| Outside areas and boundaries       | Visually inspected.   |
|                                    | The property benefits from communal garden grounds located to the rear elevation. The boundaries are of mixed type. |
|                                    |   |

| Ceilings | Visually inspected from floor level.   |  |  |  |  |
|----------|--|--|--|--|--|
|          | Plaster and artex finishes noted. Vinyl finishes are present within the shower room. |  |  |  |  |

| Internal walls              | Visually inspected from floor level.   |
|-----------------------------|--|
|                             | Using a moisture meter, walls were randomly tested for dampness where considered appropriate.  |
|                             | Plaster finishes. Vinyl finishes are present within the shower room.                           |
|                             |  |
| Floors including sub floors | Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted. |

|  | Ca | ipers of | 11001  | covern  | iys wei   | emieu     |         |     |  |
|--|----|----------|--------|---------|-----------|-----------|---------|-----|--|
|  | Th | e floors | throug | hout ha | ve fitteo | d floor c | overing | gs. |  |
|  |    |          |        |         |           |           |         |     |  |
|  |    |          |        |         |           |           |         |     |  |

| Internal joinery and kitchen fittings | Built-in cupboards were looked into but no stored items were moved.  |
|---------------------------------------|--|
|                                       | Kitchen units were visually inspected excluding appliances.  |
|                                       | The kitchen fittings are of a wall and base type. The internal doors, skirtings and facings are of a timber variety. |

| Chimney breasts and fireplaces | Visually inspected.  |
|--------------------------------|--|
|                                | No testing of the flues or fittings was carried out.                     |
|                                | The fireplace in the living room has been fitted with a gas back boiler. |

| Internal decorations | Visually inspected.             |
|----------------------|---------------------------------|
|                      | Papered and painted throughout. |

| Cellars | None. |
|---------|-------|
|         |       |

| Electricity | Accessible parts of the wiring were visually inspected without<br>removing fittings. No tests whatsoever were carried out to the<br>system or appliances. Visual inspection does not assess any<br>services to make sure they work properly and efficiently and<br>meet modern standards. If any services are turned off, the<br>surveyor will state that in the report and will not turn them on.<br>Mains supply with the fuseboard located within the hall cupboard. |
|-------------|---|
|             |   |
| Gas         | Accessible parts of the system were visually inspected without<br>removing fittings. No tests whatsoever were carried out to the<br>system or appliances. Visual inspection does not assess any   |

| removing fittings. No tests whatsoever were carried out to the<br>system or appliances. Visual inspection does not assess any<br>services to make sure they work properly and efficiently and<br>meet modern standards. If any services are turned off, the<br>surveyor will state that in the report and will not turn them on. |
|--|
| Mains supply with the gas meter located in the kitchen.  |

| Water, plumbing, bathroom fittings | Visual inspection of the accessible pipework, water tanks,<br>cylinders and fittings without removing any insulation.<br>No tests whatsoever were carried out to the system or<br>appliances.                                    |
|------------------------------------|--|
|                                    | Water is from the mains supply. The plumbing, where seen, is of copper supply pipes and PVC waste pipes. The sanitary fittings are located within the shower room. A PVC cold water storage is present within the hall cupboard. |


| Heating and hot water | Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.  |
|-----------------------|--|
|                       | No tests whatsoever were carried out to the system or appliances.  |
|                       | The property benefits from a gas fired central heating system which<br>is serviced via the gas back boiler in the living room. Hot water is<br>provided via the hot water cylinder located in the hall cupboard. |

| Drainage | Drainage covers etc. were not lifted.            |
|----------|--|
|          | Neither drains nor drainage systems were tested. |
|          | Presumed to main public sewer.                   |

| Fire, smoke and burglar alarms | Visually inspected.  |
|--------------------------------|--|
|                                | No tests whatsoever were carried out to the system or appliances.  |
|                                | All Scottish homes require a smoke alarm to be installed in the<br>room most frequently used for living purposes and in every<br>circulation space on each floor. A heat alarm also needs to be<br>installed in each kitchen. The alarms need to be ceiling mounted<br>and interlinked. Where there is a carbon-fuelled appliance such as<br>a boiler, open fire or wood burner, a carbon monoxide detector is<br>also required. We have not assessed or tested any existing<br>equipment and it is the purchasers responsibility to confirm that the<br>property will comply with these standards following a change of<br>ownership. |

| Any additional limits to inspection | For flats / maisonettes   |
|-------------------------------------|---|
|                                     | Only the subject flat and internal communal areas giving access to the flat were inspected.   |
|                                     | If the roof space or under-building / basement is communal,<br>reasonable and safe access is not always possible. If no<br>inspection was possible, this will be stated. If no inspection<br>was possible, the surveyor will assume that there are no<br>defects that will have a material effect on the valuation. |
|                                     | The building containing the flat, including any external<br>communal areas, was visually inspected only to the extent that<br>the surveyor is able to give an opinion on the general<br>condition and standard of maintenance.  |

| The property was fully floor covered/furnished at the time of inspection. The cupboards were full of possessions at the time of inspection. No access was gained to any sub floor areas. No access was gained to the area below the sanitary fittings. No access was gained to the roof void due to the position of the access hatch in respect of health and safety regulations. The roof decks and chimneys were seen from ground floor level only. The roof and rainwater goods were not monitored under wet weather conditions. At the time of inspection conditions were dry. The services were not tested. The heating system was not tested. The roof void was unseen. |
|---|
| An inspection for Japanese Knotweed was not carried out. This is a<br>plant which is subject to control regulation, is considered to be<br>invasive and one which can render a property unsuitable for some<br>mortgage lenders. It is therefore assumed that there is no Japanese<br>Knotweed within the boundaries of the property or its neighbouring<br>property. Identification of Japanese Knotweed is best undertaken<br>by a specialist contractor.   |



#### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

| Category 3 | Category 2  | Category 1 |
|------------|---|------------|
|            | Repairs or replacement requiring future attention, but estimates are still advised. |            |

| Structural movement |   |
|---------------------|---|
| Repair category     | 1   |
| Notes               | No significant structural movement noted at the time of inspection. |

| Dampness, rot and infestation |  |
|-------------------------------|--|
| Repair category               | 1  |
| Notes                         | Random damp meter readings were taken throughout using a moisture meter but<br>no significant recordings were noted. For the purposes of this report we presume<br>that those areas not inspected are free of defects. |

| Chimney stacks  |   |
|-----------------|---|
| Repair category | 2   |
| Notes           | Ongoing maintenance to the chimney stacks should be anticipated in accordance with good practice. |

| Roofing including roof space |   |
|------------------------------|---|
| Repair category              | 2   |
| Notes                        | Weathering and moss growth noted to the roof tiles. Remedial works required<br>and advice should be sought from a Roofing Contractor in accordance with good<br>practice prior to purchase. |

| Rainwater fittings |   |
|--------------------|---|
| Repair category    | 2   |
| Notes              | Corrosion noted to sections of the rainwater goods. Remedial works required including repairs to adjacent areas if necessary. All rainwater goods should be monitored under wet weather conditions. |

| Main walls      |  |
|-----------------|--|
| Repair category | 2  |
| Notes           | Weathering has occurred to sections of the rendering and pointed brickwork<br>together with cracking to the rear external communal access steps. Maintenance<br>and repair will required.<br>The cast iron window box to the front elevation and cast iron railings to the rear<br>elevation balcony will require ongoing maintenance as they are showing signs of<br>corrosion. |

| Windows, external doors and joinery |  |
|-------------------------------------|--|
| Repair category                     | 1  |
| Notes                               | Random windows were opened and found to operational. In accordance with good practice, we recommend that all windows be checked prior to purchase. |

| External decorations |  |
|----------------------|--|
| Repair category      | 1  |
| Notes                | The paint finishes will require ongoing maintenance. |

| Conservatories/porches |       |
|------------------------|-------|
| Repair category        | -     |
| Notes                  | None. |

| Communal areas  |  |
|-----------------|--|
| Repair category | 1  |
| Notes           | Cracking noted to the communal stairwell floor. Weathering has occurred to the communal stairwell windows. |

| Garages and permanent outbuildings |       |
|------------------------------------|-------|
| Repair category                    | -     |
| Notes                              | None. |

| Outside areas and boundaries |   |
|------------------------------|---|
| Repair category              | 2   |
| Notes                        | Ongoing maintenance/repair to the boundary walls and fencing should be anticipated. The tree within the rear communal garden will require to be maintained. |

| Ceilings        |  |
|-----------------|--|
| Repair category | 1  |
| Notes           | We presume the artex ceiling coatings do not contain any hazardous type materials. The timber lined ceiling within the kitchen is bowed. |

| Internal walls  |                           |
|-----------------|---------------------------|
| Repair category | 1                         |
| Notes           | No serious defects noted. |

| Floors including sub-floors |                         |
|-----------------------------|-------------------------|
| Repair category             | 1                       |
| Notes                       | Springy flooring noted. |

| Internal joinery and kitchen fittings |  |
|---------------------------------------|--|
| Repair category                       | 1  |
| Notes                                 | We would recommend that safety glass be installed to internal areas where not already present. |

| Chimney breasts and fireplaces |  |
|--------------------------------|--|
| Repair category                | 1  |
| Notes                          | Prior to use, any fireplace, flue or chimney should be checked and made good by a suitable contractor. |

| Internal decorations |                           |
|----------------------|---------------------------|
| Repair category      | 1                         |
| Notes                | No serious defects noted. |

| Cellars         |       |
|-----------------|-------|
| Repair category | -     |
| Notes           | None. |

| Electricity     |   |
|-----------------|---|
| Repair category | 2   |
| Notes           | The electrical wiring system is dated and recommend it be checked and upgraded by a Registered Electrician. |
|                 | No tests were carried out by this firm.   |

| Gas             |  |
|-----------------|--|
| Repair category | 1  |
| Notes           | We presume the gas supply is free of defects, however, the system has not been tested. |

| Water, plumbing and bathroom fittings |   |
|---------------------------------------|---|
| Repair category                       | 1   |
| Notes                                 | We presume the sealants around the sanitary fittings are functional and no defects are present to the adjacent areas. A precautionary check of the areas below and adjacent to the sanitary fittings is always recommended prior to purchase as these areas are prone to leakage. |

| Heating and hot water |  |
|-----------------------|--|
| Repair category       | 2  |
| Notes                 | The gas back boiler is dated with some dated radiators noted . A precautionary check of the heating and hot water system is recommended in accordance with good practice by a Registered Heating Engineer and any necessary remedial works carried out prior to purchase.<br>No tests were carried out by this firm. |

| Drainage        |   |
|-----------------|---|
| Repair category | 1   |
| Notes           | We presume the drainage system is free of defects, however, the system has not been tested. |

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

| Structural movement                   | 1 |
|---------------------------------------|---|
| Dampness, rot and infestation         | 1 |
| Chimney stacks                        | 2 |
| Roofing including roof space          | 2 |
| Rainwater fittings                    | 2 |
| Main walls                            | 2 |
| Windows, external doors and joinery   | 1 |
| External decorations                  | 1 |
| Conservatories/porches                | - |
| Communal areas                        | 1 |
| Garages and permanent outbuildings    | - |
| Outside areas and boundaries          | 2 |
| Ceilings                              | 1 |
| Internal walls                        | 1 |
| Floors including sub-floors           | 1 |
| Internal joinery and kitchen fittings | 1 |
| Chimney breasts and fireplaces        | 1 |
| Internal decorations                  | 1 |
| Cellars                               | - |
| Electricity                           | 2 |
| Gas                                   | 1 |
| Water, plumbing and bathroom fittings | 1 |
| Heating and hot water                 | 2 |
| Drainage                              | 1 |

#### **Category 3**

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

#### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. Accessibility information

#### Guidance notes on accessibility information

#### Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

#### Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

| 1. Which floor(s) is the living accommodation on?                                      | First    |
|--|----------|
| 2. Are there three steps or fewer to a main entrance door of the property?             | Yes No X |
| 3. Is there a lift to the main entrance door of the property?                          | Yes No X |
| 4. Are all door openings greater than 750mm?   | Yes No X |
| 5. Is there a toilet on the same level as the living room and kitchen?                 | Yes X No |
| 6. Is there a toilet on the same level as a bedroom?                                   | Yes X No |
| 7. Are all rooms on the same level with no internal steps or stairs?                   | Yes X No |
| 8. Is there unrestricted parking within 25 metres of an entrance door to the building? | Yes X No |

#### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

Replacement windows have been installed.

Where areas of maintenance, defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialist's or contractor's advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

#### Estimated reinstatement cost for insurance purposes

For Reinstatement Cost Assessment purposes, it is recommended that the subjects be insured for a sum of not less than £300,000 (Three Hundred Thousand Pounds Sterling). This figure is the estimate of the cost of rebuilding the premises and bears no direct relationship to current market value.

#### Valuation and market comments

Having considered matters, taking account of our general observations on site, we are of the opinion that the Market Value of the subjects in their present condition and with the benefit of vacant possession may be fairly stated in the sum of £290,000 (Two Hundred and Ninety Thousand Pounds Sterling).

Market conditions are steady at the present time.

| Signed         | Security Print Code [603778 = 5918 ]<br>Electronically signed |
|----------------|---|
| Report author  | D Lewis   |
| Company name   | J & E Shepherd  |
| Address        | 12 Atholl Crescent, Edinburgh, EH3 8HA                        |
| Date of report | 22nd April 2025   |

### Mortgage Valuation Report



| Property Address                                |   |                         |                              |  |
|---|---|-------------------------|------------------------------|--|
| Address<br>Seller's Name<br>Date of Inspection  | 1F1, 15 WARRIS<br>Lesley Scarles &<br>15th April 2025 |                         | ARRISTON, EDINBU             | RGH, EH3 5LY   |
| Property Details                                |   |                         |                              |  |
| Property Type                                   | House X Purpose built flat                            | Bungalow Converted flat | Purpose built maisor         | ette Converted maisonette<br>Flat over non-residential use<br>Other (specify in General Remarks) |
| Property Style                                  | Detached  | Semi detached           | Mid terrace                  | End terrace  |
|   | Back to back  | High rise block         | X Low rise block             | Other (specify in General Remarks)   |
| Does the surveyor be<br>e.g. local authority, m |   | erty was built for      | the public sector,           | Yes X No   |
| Flats/Maisonettes on                            | y Floor(s) on which                                   | located 1               | No. of floors in block       | 3 Lift provided? Yes X No  |
| Approximate Year of                             | Construction 1960                                     |                         | No. of units in block        | 6  |
| Tenure  |   |                         |                              |  |
| X Absolute Ownership                            | Leasehold   | Ground rent £           | Unexpire                     | d years  |
| Accommodation                                   |   |                         |                              |  |
| Number of Rooms                                 | 1 Living room(s)                                      | 2 Bedroom(s)            | 1 Kitchen(s)                 |  |
|   | 1 Bathroom(s)   | 0 WC(s)                 | 0 Other (Specify in G        | eneral remarks)  |
| Gross Floor Area (ex                            |   |                         | 72 m <sup>2</sup> (Internal) | m² (External)  |
| Residential Element                             | (greater than 40%)                                    | X Yes No                |                              |  |
| Garage / Parking /                              | Outbuildings  |                         |                              |  |
| Single garage                                   | Double garage   | Parki                   | ng space                     | X No garage / garage space / parking space   |
| Available on site?                              | Yes No  |                         |                              |  |
| Permanent outbuildin                            | igs:  |                         |                              |  |
| None.   |   |                         |                              |  |

### Mortgage Valuation Report

| Construction                             |                |                     |                       |                        |                 |                   |                |
|--|----------------|---------------------|-----------------------|------------------------|-----------------|-------------------|----------------|
| Walls                                    | X Brick        | Stone               |                       | Timber frame           | Othe            | r (specify in Ger | neral Remarks) |
| Roof                                     | X Tile         | Slate               | Asphalt               | Felt                   | Othe            | r (specify in Ger | neral Remarks) |
| Special Risks                            |                |                     |                       |                        |                 |                   |                |
| Has the property                         | suffered strue | ctural movem        | ent?                  |                        |                 | Yes               | X No           |
| If Yes, is this rece                     | ent or progres | ssive?              |                       |                        |                 | Yes               | No             |
| Is there evidence,<br>immediate vicinity |                | eason to antic      | ipate subsidence      | , heave, landslip      | or flood in the | e Yes             | X No           |
| If Yes to any of th                      | e above, pro   | vide details in     | General Remark        | (S.                    |                 |                   |                |
| Service Connec                           | ctions         |                     |                       |                        |                 |                   |                |
| Based on visual ir of the supply in G    |                |                     | ices appear to be     | e non-mains, plea      | se comment      | on the type a     | and location   |
| Drainage                                 | X Mains        | Private             | None                  | Water                  | X Mains         | Private           | None           |
| Electricity                              | X Mains        | Private             | None                  | Gas                    | X Mains         | Private           | None           |
| Central Heating                          | X Yes          | Partial             | None                  |                        |                 |                   |                |
| Brief description of                     | of Central He  | ating:              |                       |                        |                 |                   |                |
| Gas fired with st                        | eel radiators  |                     |                       |                        |                 |                   |                |
| Site                                     |                |                     |                       |                        |                 |                   |                |
| Apparent legal iss                       | sues to be ve  | rified by the c     | onveyancer. Ple       | ase provide a brie     | ef description  | in General R      | Remarks.       |
| Rights of way                            | X Shared dr    | ives / access       | Garage or other       | amenities on separat   | e site 🗌 Sha    | red service conr  | nections       |
| III-defined boundar                      | ries           | Agricu              | tural land included w | ith property           | Othe            | er (specify in Ge | neral Remarks) |
| Location                                 |                |                     |                       |                        |                 |                   |                |
| Residential suburb                       | x R            | esidential within t | own / city 🗌 Mixe     | ed residential / comme | ercial 🗌 Maiı   | nly commercial    |                |
| Commuter village                         | R              | emote village       | Isola                 | ated rural property    | Othe            | er (specify in Ge | neral Remarks) |
| Planning Issue                           | S              |                     |                       |                        |                 |                   |                |
| Has the property                         | been extende   | ed / converted      | I / altered?          | Yes X No               |                 |                   |                |
| If Yes provide det                       | ails in Gener  | al Remarks.         |                       |                        |                 |                   |                |
| Roads                                    |                |                     |                       |                        |                 |                   |                |
| X Made up road                           | Unmade ro      | ad 🗌 Partly         | completed new road    | I Pedestrian           | access only     | Adopted           | Unadopted      |

#### **General Remarks**

Replacement windows have been installed. 2. Maintenance and repair is required to the external fabric, in particular the main walls, roof, chimneys, rainwater goods and balcony. 3. Ongoing maintenance to the boundary walls and fencing should be anticipated. The tree within the rear communal garden will require to be maintained.
 The electrical wiring system is dated.

#### **Essential Repairs**

| None.                                 |                        |    |          |
|---------------------------------------|------------------------|----|----------|
|                                       |                        |    |          |
|                                       |                        |    |          |
|                                       |                        |    |          |
|                                       |                        |    |          |
|                                       |                        |    |          |
|                                       |                        |    |          |
|                                       |                        |    |          |
|                                       |                        |    |          |
| Estimated cost of essential repairs £ | Retention recommended? | No | Amount £ |

## Mortgage Valuation Report

#### **Comment on Mortgageability**

| The property forms suitable security for mortgage purposes subject to the specific lending criteria of mortgage provider.                 | fany      |
|---|-----------|
|   |           |
| Valuations  |           |
| Market value in present condition   | £ 290,000 |
| Market value on completion of essential repairs   | £n/a      |
| Insurance reinstatement value<br>(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT) | £ 300,000 |
| Is a reinspection necessary?  | Yes X No  |
| Buy To Let Cases  |           |
| What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis?       | £         |
| Is the property in an area where there is a steady demand for rented accommodation of this type?  | Yes No    |
| Declaration   |           |

| Signed                      | Security Print Code [603778 = 5918 ]<br>Electronically signed by:- |
|-----------------------------|--|
| Surveyor's name             | D Lewis  |
| Professional qualifications | BSC MRICS  |
| Company name                | J & E Shepherd   |
| Address                     | 12 Atholl Crescent, Edinburgh, EH3 8HA                             |
| Telephone                   | 0131 225 1234  |
| Fax                         | 0131 220 3178  |
| Report date                 | 22nd April 2025  |



## Property Questionnaire



| Property address | 15/3 Warriston Drive |
|------------------|----------------------|
|                  | Edinburgh            |
|                  | EH3 5LY              |
|                  |                      |
|                  |                      |
|                  |                      |
|                  |                      |
|                  |                      |

| Seller(s) | Stuart & Lesley Scarles |
|-----------|-------------------------|
|           |                         |

| Completion date of property questionnaire | 16 April 2025 |
|---|---------------|
|---|---------------|

#### Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

### Information to be given to prospective buyer(s)

| 1. | Length of ownership   |
|----|---|
|    | How long have you owned the property? 13 years 10months   |
| 2. | Council tax   |
|    | Which Council Tax band is your property in? (Please tick one) D   |
| 3. | Parking   |
|    | What are the arrangements for parking at your property?<br>(Please tick all that apply)<br>• Resident permit<br>• Metered parking |
|    |   |
| 4. | Conservation area   |

|  | Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)? | No |
|--|--|----|
|--|--|----|

| 5. | Listed buildings  |             |  |  |
|----|---|-------------|--|--|
|    | Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?                        | No          |  |  |
| 6. | Alterations/additions/extensions  |             |  |  |
| a. | (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? | No          |  |  |
|    | <u>If you have answered yes</u> , please describe below the changes which you have made:  |             |  |  |
|    | (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?   |             |  |  |
|    | If you have answered yes, the relevant documents will be needed by<br>the purchaser and you should give them to your solicitor as soon as<br>possible for checking.                       |             |  |  |
|    | If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:                                      |             |  |  |
| b. | Have you had replacement windows, doors, patio doors or double glazing installed in your property?  | Yes         |  |  |
|    | If you have answered yes, please answer the three questions below:  |             |  |  |
|    | (i) Were the replacements the same shape and type as the ones you replaced?   | Same shape  |  |  |
|    | (ii) Did this work involve any changes to the window or door openings?  | No          |  |  |
|    | (iii) Please describe the changes made to the windows doors, or patio approximate dates when the work was completed):<br>2015   | doors (with |  |  |
|    | pening format.  |             |  |  |
|    |   |             |  |  |
|    | Please give any guarantees which you received for this work to your solicitor or estate agent.  |             |  |  |

| 7. | Central heating   |   |  |
|----|---|---|--|
| а. | Is there a central heating system in your property?<br>(Note: a partial central heating system is one which does not heat all<br>the main rooms of the property —<br>the main living room, the bedroom(s), the hall and the bathroom).<br><u>If you have answered yes or partial</u> – what kind of central heating is<br>there?<br>(Examples: gas-fired, solid fuel, electric storage heating, gas warm<br>air). | Yes<br>Gas-fired  |  |
|    | If you have answered yes, please answer the three questions below:(i)When was your central heating system or partial central heating<br>Don't know  | g system installed?                                       |  |
|    | <ul> <li>(ii) Do you have a maintenance contract for the central heating system?</li> <li>If you have answered yes, please give details of the company with which you have a maintenance contract:</li> </ul>   | No but serviced<br>annually by<br>Contract Heating<br>Ltd |  |
|    | (iii) When was your maintenance agreement last renewed? (Please and year).  | provide the month   |  |
| 8. | Energy Performance Certificate  |   |  |
|    | Does your property have an Energy Performance Certificate which is less than 10 years old?  | No  |  |
| 9. | Issues that may have affected your property   |   |  |
| a. | Has there been any storm, flood, fire or other structural damage to your property while you have owned it?  | No  |  |
|    | <u>If you have answered yes</u> , is the damage the subject of any outstanding insurance claim?   | No  |  |
| b. | Are you aware of the existence of asbestos in your property?<br>If you have answered yes, please give details:  | No  |  |

| 10.   | Services  |    |  |
|---|---|----|--|
| a. Please tick which services are connected to your property and give details of the supplier:<br>Services Connected Supplier<br>Gas or liquid petroleum gas Mains EDF<br>Water mains or private water supply Mains Scottish Water<br>Electricity Mains EDF<br>Mains drainage<br>Telephone Virgin Media<br>Cable TV or satellite Virgin Media<br>Broadband Virgin Media |   |    |  |
| b.  | Is there a septic tank system at your property?<br><u>If you have answered yes</u> , please answer the two questions below:   | No |  |
|   | (iv) Do you have appropriate consents for the discharge from your septic tank?  |    |  |
|   | (v) Do you have a maintenance contract for your septic tank?<br><u>If you have answered yes</u> , please give details of the company with<br>which you have a maintenance contract: |    |  |

| 11. | Responsibilities for shared or common areas   |  |
|-----|---|--|
| а.  | Are you aware of any responsibility to contribute to the cost of<br>anything used jointly, such as the repair of a shared drive, private<br>road, boundary, or garden area?<br>If you have answered yes, please give details:   | Yes<br>Rear boundary<br>wall<br>Garden       |
| ь.  | Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?<br>If you have answered yes, please give details:  | Yes<br>Roof<br>Stairwell and<br>common areas |
| с.  | Has there been any major repair or replacement of any part of the roof during the time you have owned the property?   | No   |
| d.  | Do you have the right to walk over any of your neighbours' property<br>— for example to put out your rubbish bin or to maintain your<br>boundaries?<br><u>If you have answered yes</u> , please give details:   | No   |
| e.  | As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?<br><u>If you have answered yes</u> , please give details:                                       | No   |
| f.  | As far as you are aware, is there a public right of way across any part<br>of your property? (public right of way is a way over which the public<br>has a right to pass, whether or not the land is privately-owned.)<br>If you have answered yes, please give details: | No   |
| 12. | Charges associated with your property   |  |
| а.  | Is there a factor or property manager for your property?<br><u>If you have answered yes</u> , please provide the name and address, and<br>give details of any deposit held and approximate charges:   | No   |

| b.  | Is there a common buildings insurance policy?  | No |  |
|-----|--|----|--|
|     | If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?   |    |  |
| с.  | Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.   |    |  |
| 13. | Specialist works   |    |  |
| а.  | As far as you are aware, has treatment of dry rot, wet rot, damp or<br>any other specialist work ever been carried out to your property?<br><u>If you have answered yes</u> , please say what the repairs were for,<br>whether you carried out the repairs (and when) or if they were done<br>before you bought the property.  | No |  |
| b.  | As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?<br>If you have answered yes, please give details:   | No |  |
| с.  | <u>If you have answered yes</u> to 13(a) or (b), do you have any<br>guarantees relating to this work?<br><u>If you have answered yes</u> , these guarantees will be needed by the<br>purchaser and should be given to your solicitor as soon as possible<br>for checking. If you do not have them yourself <u>please write below</u><br><u>who has these documents</u> and your solicitor or estate agent will<br>arrange for them to be obtained. You will also need to provide a<br>description of the work carried out. This may be shown in the original<br>estimate.<br>Guarantees are held by: |    |  |

| 14.   | Guarantees   |    |     |               |                     |      |
|-------|--|----|-----|---------------|---------------------|------|
| а.    | Are there any guarantees or warranties for any of the following:   |    |     |               |                     |      |
|       |  | No | Yes | Don't<br>know | With title<br>deeds | Lost |
| (i)   | Electrical work  | Х  |     |               |                     |      |
| (ii)  | Roofing  | Х  |     |               |                     |      |
| (iii) | Central heating  | Х  |     |               |                     |      |
| (iv)  | National House Building Council (NHBC)   | Х  |     |               |                     |      |
| (v)   | Damp course  | Х  |     |               |                     |      |
| (vi)  | Any other work or installations?<br>(for example, cavity wall insulation,<br>underpinning, indemnity policy)                                   | x  |     |               |                     |      |
| b.    | <u>If you have answered 'yes'</u> or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s): |    |     |               |                     |      |
| с.    | Are there any outstanding claims under any of the guarantees listed above?<br>If you have answered yes, please give details:                   |    |     | No            |                     |      |
| 15.   | Boundaries   |    |     |               |                     |      |
|       | So far as you are aware, has any boundary of your property been moved in the last 10 years?<br>If you have answered yes, please give details:  |    |     | No            |                     |      |

| 16. | Notices that affect your property   |    |  |  |
|-----|---|----|--|--|
|     | In the past three years have you ever received a notice:  |    |  |  |
| a.  | advising that the owner of a neighbouring property has made a planning application?   | No |  |  |
| b.  | that affects your property in some other way?   | No |  |  |
| с.  | that requires you to do any maintenance, repairs or improvements to your property?  | No |  |  |
|     | If you have answered yes to any of $a-c$ above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property. |    |  |  |

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s) :

Stuart Scarles

Date: 16 April 2025

### shepherd.co.uk



#### **Home Report** Valuation Report Mortgage & Re-Mortgage Valuation **Executory Valuation Inheritance Tax Valuation Tax Valuation** Separation Valuation **Private Sale Valuation** New Build, Development & Plot Valuation **Extension & Alteration Valuation Insurance Reinstatement Valuation Portfolio Valuation Rental Valuation Driveby Valuation Desktop Valuation Energy Performance Certificate (EPC)** Level Two Survey & Valuation Report Level Two Condition Report **Expert Witness Report Council Tax Appeal**



Commercial Valuation Commercial Agency Acquisitions & Disposals Commercial Lease Advisory Rent Reviews Asset Management Project Consultancy Development Appraisals Rating Commercial Property Auctions Property Management Professional Services Licensed Trade / Leisure



Quantity Surveying Building Surveying Project Management Dispute Resolution Support Services Principal Designer Clerk of Works Commercial EPC Fire Engineering Health & Safety Management Employer's Agent Energy Department Housing Services Development Monitoring Mediation Services

**Aberdeen** △ ▲ △ 01224 202800

**Ayr** △ ▲ 01292 267987

**Bearsden** △▲ 0141 611 1500

Birmingham ▲ 0121 270 2266

**Coatbridge** △ ▲ 01236 436561

Cumbernauld △ ▲ 01236 780000

**Dalkeith** △▲ 0131 663 2780 **Dumbarton** △▲ 01389 731682

**Dumfries** △▲△ 01387 264333

**Dundee** △ ▲ 01382 200454 ▲ 01382 220699

**Dunfermline** △ ▲ 01383 722337 △ 01383 731841

**East Kilbride** △ ▲ 01355 248535

**Edinburgh** △ ▲ 0131 2251234

△ ▲ 0131 2251234 △ 0131 557 9300 **Elgin** △▲ 01343 553939

**Falkirk** △▲ 01324 635 999

△ ▲ 01346 517456 Galashiels

Fraserburgh

△ △ 01896 750150 **Glasgow** △ △ △ 0141 331 2807

**Glasgow South** △ ▲ 0141 649 8020

**Glasgow West End** △ ▲ 0141 353 2080 **Greenock** △ ▲ 01475 730717

**Hamilton** △ ▲ 01698 897548

Inverness △▲△01463 712239

**Kilmarnock** △ ▲ 01563 520318

**Kirkcaldy** △ ▲ 01592 205442

**Leeds** △ 0113 322 5069

**Livingston** ▲▲01506 416777 **London** ▲ △ 02033 761 236

Montrose △ ▲ 01674 676768

Motherwell △ ▲ 01698 252229

Musselburgh △▲ 0131 653 3456

**Oban** △▲ 01631 707 800

**Paisley** ▲ ▲ 0141 889 8334

**Perth** ▲ ▲ 01738 638188 △ 01738 631631 **Peterhead** ▲ 01779 470766

**St Andrews** ▲ ▲ 01334 477773 △ 01334 476469

Saltcoats ▲ ▲ 01294 464228

**Stirling** ▲ ▲ 01786 450438 △ 01786 474476